Inspected by: Herman ATS ATS



Brand:	Kia	Mileage(km):	22783
Model:	Sportage	Number of doors:	5
Model type:	1.6 GDI DynamicLine	Vehicle length (cm):	
License plate:	472056	Vehicle width (cm):	
Report code:	2056	Vehicle height (cm):	
Chassis number:	U5YPG814AJL472056	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	24/05/2018	Power(kw):	97
First NL reg.:		Transmission	Manual
Color:	Anthracite Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1600
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (q/km):	
Cargo space (I):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Licht Sensor
- ABS
- Fog lamps
- Start/stop system
- Power steering
- Multifunctional steering wheel
- Remote central locking
- 2222222222222
- Roof rail (silver) Metallic finish
- Halogen headlights
- Exterior mirrors in car body color

- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Rear-seat folding (unequal parts)
- ~ Inflatable set
- Aux connection
- USB connection Bluetooth streaming
- $\overline{\mathbf{v}}$ DAB+
- Bluetooth car kit
- Radio

- Cruise control
- Airconditioning
- Large screen navigation
- Electrically operated rear windows
 Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors Central armrest front
- Audio control on the steering wheel
- Leather steering wheel Airbag(s) front + flank + other

🗱 Tires

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Summer	Alloy	225/60 R17		4
Tire left rear	Summer	Alloy	225/60 R17		7
Tire right front	Summer	Alloy	225/60 R17		4
Tire right rear	Summer	Δllov	225/60 P17		7

A Additional information No. of keys: 2 Luxury key Instruction booklet Airco works Interior color: Anthracite Maintenance booklet: (door dealer) Odorless Upholstery: Stof Clean inside (Interior is clean) No. of seats: Stamp date: 29/11/2023 Display ok No. of headrests: Last turn mileage(km): 19646 Vehicle special usage (None)

A Cleaning

- Clean inside (Interior is clean)
- Clean outside



Front bumper - Scratch



Front left screen - Scratch

▶ Damages



Roof - Scratch



Roof - Restyle dent

Claimed fields

Voorbumper / Kras(sen) / Spuiten







Dak / Kras(sen) / Polijsten



Dak / Restyle Deukje(s) / Restylen

€ 0

Acceptable



♥ Extra options













































