Inspected by: Herman ATS ATS



Brand:	Renault	Mileage(km):	45389
			10000
Model:	Captur	Number of doors:	5
Model type:	1.6 PHEV Intens Aut.	Vehicle length (cm):	
License plate:	756934	Vehicle width (cm):	
Report code:	6934	Vehicle height (cm):	
Chassis number:	VF1RJB00066756934	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	30/03/2021	Power(kw):	118
First NL reg.:		Transmission	Automatic
Color:	Anthracite Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1600
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Hybride (Electro/Benzine) plug-in
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (q/km):	
Cargo space (I):		Nb. of Axles:	2

🗱 opties

- Alloy wheels
- Digital dashboard
- Licht Sensor
- SASSASASASASASAS ABS
- Start/stop system
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Metallic finish
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor

- Rear wiper
- Rear view camera
- Rear parking sensors
- 222222 Front parking sensors
- Towbar with detachable ball
- Luggage cover
- Charging cable 220V Inflatable set
- $\overline{\mathbf{v}}$ Aux connection
- USB connection
- Bluetooth streaming
- NVV DAB+
- Bluetooth car kit
- Radio

- Cruise control
- Climate control (digital)
- Large screen navigation
- Keyless entry/start/stop Electrically operated rear windows Electrically operated front windows Electrically folding mirrors

- Electrically adjustable mirrors
- Central armrest front Audio control on the steering wheel
- Leather steering wheel
- Lane assistance
- Airbag(s) front + flank + other

200	Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front			015/55 010	0	
Tire left front	Summer	Alloy	215/55 R18	Goodyear	5
Tire left rear	Summer	Alloy	215/55 R18	Michelin	7
Tire right front	Summer	Alloy	215/55 R18	Goodyear	5
Tire right rear	Summer	Alloy	215/55 R18	Michelin	7

A A I I'	al information
A Additions	ai intormation

Additional information	•		
No. of keys:	1 Luxury key	☐ Instruction booklet	✓ Airco works
Interior color:	Anthracite	Maintenance booklet:	⊘ Odorless
Upholstery:	Half stof/leder		Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	☑ Display ok
No. of headrests:	5	Last turn mileage(km):	✓ Vehicle special usage (None)

A Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages



Rear bumper - Scratch

Damages





Rear right door - Restyle dent

Claimed fields

€ n

RA portier / Restyle Deukje(s) / Restylen

Achterbumper / Kras(sen) / Spuiten





🗱 Extra options

































