### Inspected by: Herman ATS ATS



Brand:	Volkswagen	Mileage(km):	86560
Model:	Tiguan	Number of doors:	5
Model type:	1.5 TSI ACT Highline Business R	Vehicle length (cm):	
License plate:	H587FD	Vehicle width (cm):	
Report code:	4988	Vehicle height (cm):	
Chassis number:	WVGZZZ5NZLW854988	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	28/01/2020	Power(kw):	110
First NL req.:	28/01/2020	Transmission	Automatic
Color:	Grey Metallic	Number of gears	7
Weight (kg)(kg):	1540	Displacement(cc):	1495
Empty weight(kg):	1440	Number of cylinders:	4
Wheelbase (cm)(cm):	268	Fuel type:	Petrol
Top speed (km/h):	200	Fuel tank capacity:	
Cons. in the city (I/100 km):	7	EU category:	Euro 6
Cons. outside the city (I/100 km):	5.1	Energy label:	С
Avarage consumption (I/100 km):	5.8	NL Tax Rate %:	
Acceleration (s):	9.2	CO2 (q/km):	132
Cargo space (I):	1540	Nb. of Axles:	2
Perm. max weight (kg):	2100	APK date:	28/01/2026

#### opties 🚓

Alloy wheels

Digital dashboard Licht Sensor

ABS

Fog lamps

Start/stop system

Power steering

Front seats adjustable in height

Multifunctional steering wheel

Remote central locking

Roof rail (silver)

Metallic finish

LED headlights

LED rear lights Exterior mirrors in car body color

Privacy glass

Rain sensor

Rear wiper Rear parking sensors Front parking sensors

Rear-seat folding (equal parts)

Rear-seat folding (unequal parts)

1466 Ski hatch

~

Luggage cover Trunk opens electrically  ${f \checkmark}$ 

 $[ \checkmark ]$ Inflatable set

 ${f \checkmark}$ Aux connection

USB connection Bluetooth streaming

DAB+

\ \ \ \ \ Radio/CD player Bluetooth car kit

WiFi

\ \ \ Cruise control (adaptive)

Cruise control

Black top interior  $\sim$ 

Airconditioning in the back

Climate control

Climate control (digital)

Climate control (L/R separated)

Large screen navigation

Electrically operated rear windows Electrically operated front windows

Electrically adjustable mirrors

Electrically heated driver's seat

Electrically heated passenger seat

Central armrest front

Adjustable lumbar support driver's seat

Adjustable lumbar support passenger seat Audio control on the steering wheel

7777777 Leather steering wheel

Switch flippers

Lane assistance

Pedestrian safety system Dead angle assistance


Airbag(s) front + flank + other

# **C** Tires

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Summer	Alloy	255/45 R19	Pirelli	7
Tire left rear	Summer	Alloy	255/45 R19	Pirelli	5
Tire right front	Summer	Alloy	255/45 R19	Pirelli	7
Tire right rear	Summer	Alloy	255/45 R19	Pirelli	5

#### **▲** Additional information No. of keys: Luxury key Instruction booklet Airco works Interior color: Maintenance booklet: Anthracite Odorless Upholstery: Alcantara Clean inside (Interior is clean) No. of seats: Stamp date: 5 Display ok No. of headrests: Last turn mileage(km): 5 Vehicle special usage (None)

## Damages



Acceptable



Tailgate/ lid - Restyle dent



Rear bumper - Scratch

# Damages



De Onderhouds Indicator Is Actief



Front left rim - Scratch



Rear right door - Restyle dent



Front left door - Restyle dent

# Claimed fields

De Onderhouds Indicator Is Actief /



LV velg / Kras(sen) / Spuiten



RA portier / Restyle Deukje(s) / Restylen



Achterklep/deksel / Restyle Deukje(s) / Restylen



Achterbumper / Kras(sen) / Bijwerken







# **♥** Extra options

















































AUTOF CTOR