



<b>Brand:</b>	Renault	<b>Mileage(km):</b>	45837
<b>Model:</b>	Captur	<b>Number of doors:</b>	5
<b>Model type:</b>	1.0 TCe 90 Intens	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	GDP34J	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	9951	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VF1RJB00168249951	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	06/12/2021	<b>Power(kw):</b>	67
<b>First NL reg.:</b>	20/07/2024	<b>Transmission:</b>	Manual
<b>Color:</b>	Grey <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears:</b>	6
<b>Weight (kg)(ka):</b>	1296	<b>Displacement(cc):</b>	999
<b>Empty weight(kg):</b>	1196	<b>Number of cylinders:</b>	3
<b>Wheelbase (cm)(cm):</b>	264	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	168	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	B
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	14	<b>CO2 (g/km):</b>	1
<b>Cargo space (l):</b>	1296	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	1753	<b>APK date:</b>	06/12/2025

### opties

- Alloy wheels
- Licht Sensor
- ABS
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Sports package (exterior)
- Roof rail (silver)
- Metallic finish
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (equal parts)
- Rear-seat folding (unequal parts)
- Spare wheel (homecomer)
- USB connection
- Bluetooth streaming
- DAB+
- Bluetooth car kit
- Radio
- WiFi
- Cruise control
- Climate control (digital)
- Large screen navigation
- Keyless entry
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically adjustable mirrors
- Electrically adjustable passenger seat
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Lane assistance
- Pedestrian safety system
- Airbag(s) front + flank + other

### Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	215/60 R17	Continental	5
Tire left rear	Summer	Alloy	215/60 R17	Continental	4
Tire right front	Summer	Alloy	215/60 R17	Continental	5
Tire right rear	Summer	Alloy	215/60 R17	Continental	4

### Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Anthracite	<b>Maintenance booklet:</b>		<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	11/04/2024	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	45231	<input checked="" type="checkbox"/> Vehicle special usage (None)

### Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch

🔧 Damages

⊕ Acceptable



Hoedenplank Manco



Rear left door - Restyle dent

🏠 Claimed fields

€ 0

Hoedenplank Manco /

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0

LA portier / Restyle Deukje(s) / Restylen

€ 0

⚙️ Extra options



