



Brand:	Citroen	Mileage(km):	60388
Model:	C3	Number of doors:	5
Model type:	1.2 82PK Feel	Vehicle length (cm):	
License plate:	651393	Vehicle width (cm):	
Report code:	1393	Vehicle height (cm):	
Chassis number:	VF7SXHMRVKT651393	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	24/09/2019	Power(kw):	61
First NL reg.:		Transmission	Manual
Color:	Anthracite <input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(ka):		Displacement(cc):	1200
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Avarage consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Metallic finish
- LED rear lights
- Privacy glass
- Rain sensor
- Rear wiper
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Spare wheel (full)
- USB connection
- Bluetooth streaming
- DAB+
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (digital)
- Large screen navigation
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Audio control on the steering wheel
- Lane assistance
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Steel	205/55 R16	Continental	5
Tire left rear	Summer	Steel	205/55 R16	Michelin	6
Tire right front	Summer	Steel	205/55 R16	Continental	5
Tire right rear	Summer	Steel	205/55 R16	Michelin	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	(door dealer)	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	06/02/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	53202	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages

Not acceptable



Rear bumper - Scratch



Rear left door - Restyle dent



Windscreen - Pip



Rear right door - Restyle dent

🔧 Damages

🕒 Acceptable



De Bandenspanning Indicator Is Actief



Front left door - Restyle dent



Rear right screen - Restyle dent



Rear right rim - Scratch



Front bumper - Scratch

🚩 Claimed fields

€ 0

De Bandenspanning Indicator Is Actief /

€ 0

Achterbumper / Kras(sen) / Spuiten

€ 0

LA portier / Restyle Deukje(s) / Restylen

€ 0

Voorruit / Ster / Opvullen

€ 0

RV portier / Restyle Deukje(s) / Restylen

€ 0

RA portier / Restyle Deukje(s) / Restylen

€ 0

RA scherm / Restyle Deukje(s) / Restylen

€ 0

RA velg / Kras(sen) / Bijwerken

€ 0

Voorbumper / Kras(sen) / Bijwerken

€ 0

⚙️ Extra options



