



Brand:	Peugeot	Mileage(km):	62265
Model:	2008	Number of doors:	5
Model type:	1.2 130PK GT-Line Aut.	Vehicle length (cm):	
License plate:	160290	Vehicle width (cm):	
Report code:	0290	Vehicle height (cm):	
Chassis number:	VF3CUHNS4KY160290	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	26/09/2019	Power(kw):	96
First NL reg.:		Transmission:	Automatic
Color:	Blue <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):		Displacement(cc):	1200
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Licht Sensor
- ABS
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (black)
- Metallic finish
- LED headlights
- LED rear lights
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Spare wheel (homecomer)
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (digital)
- Large screen navigation
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Audio control on the steering wheel
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/50 R17	Michelin	3
Tire left rear	Winter	Alloy	205/50 R17	Michelin	3
Tire right front	Winter	Alloy	205/50 R17	Michelin	3
Tire right rear	Winter	Alloy	205/50 R17	Michelin	3
Tire left front	Summer	Alloy	205/50 R17	Goodyear	3
Tire left rear	Summer	Alloy	205/50 R17	Goodyear	3
Tire right front	Summer	Alloy	205/50 R17	Michelin	3
Tire right rear	Summer	Alloy	205/50 R17	Goodyear	3

Additional information

No. of keys:	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder		<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable



Front left rim - Scratch



Front bumper - Scratch




Front right rim - Scratch

🔧 Damages

⊕ Acceptable



Front left door - Scratch



Bonnet - Scratch



Rear left door - Scratch

👉 Claimed fields

€
0

LV velg / Kras(sen) / Bijwerken

€
0

LV portier / Kras(sen) / Bijwerken

€
0

Voorbumper / Kras(sen) / Bijwerken

€
0

Motorkap / Kras(sen) / Polijsten

€
0

RV velg / Kras(sen) / Bijwerken




€
0

LA portier / Kras(sen) / Bijwerken

€
0

⚙️ Extra options







AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE