Inspected by: Herman ATS ATS



Brand:	Peugeot	Mileage(km):	15057
Model:	208	Number of doors:	5
Model type:	1.2 100PK Allure	Vehicle length (cm):	
License plate:	176639	Vehicle width (cm):	
Report code:	6639	Vehicle height (cm):	
Chassis number:	VR3UPHNE1R4176639	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	10/07/2024	Power(kw):	74
First NL reg.:		Transmission	Manual
Color:	Grey Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1200
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (q/km):	
Cargo space (I):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Digital dashboard
- Licht Sensor
- ABS
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- रारारारारारारारारार Remote central locking
- Metallic finish
- LED headlights
- LED rear lights
- Privacy glass

- Rain sensor
- Rear wiper
- Rear parking sensors
- Front parking sensors
- Luggage cover Inflatable set
- 1
- Aux connection
- USB connection Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control

- Climate control (digital)
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Audio control on the steering wheel
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Winter	Alloy	195/65 R16	sailun	5
Tire left rear	Winter	Alloy	195/65 R16	sailun	5
Tire right front	Winter	Alloy	195/65 R16	sailun	5
Tire right rear	Winter	Alloy	195/65 R16	sailun	5

Additional information

No. of keys:	2 Luxury key	Instruction booklet	Airco works
Interior color:	Anthracite	Maintenance booklet:	Odorless
Upholstery:	Half stof/leder		Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	Display ok
No. of headrests:	5	Last turn mileage(km):	▼ Vehicle special usage (None)

A Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages



Front bumper - Scratch



Roof - Dent

Damages



Rear bumper - Scratch



Rear left screen - Scratch

LA scherm / Kras(sen) / Polijsten





Front left door - Scratch

▼ Claimed fields

Achterbumper / Kras(sen) / Polijsten



Dak / Deuk(en) / Restylen





LV portier / Kras(sen) / Bijwerken



Voorbumper / Kras(sen) / Bijwerken

€ 0



♥ Extra options

































