



Brand:	Peugeot	Mileage(km):	75044
Model:	3008	Number of doors:	5
Model type:	1.2 PureTech Allure Aut.	Vehicle length (cm):	
License plate:	G501LV	Vehicle width (cm):	
Report code:	2265	Vehicle height (cm):	
Chassis number:	VF3MRHNSUKS432265	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	11/11/2019	Power(kw):	96
First NL reg.:	11/11/2019	Transmission:	Automatic
Color:	Red <input checked="" type="checkbox"/> Metallic	Number of gears:	8
Weight (kg)(ka):	1395	Displacement(cc):	1199
Empty weight(ka):	1295	Number of cylinders:	3
Wheelbase (cm)(cm):	268	Fuel type:	Petrol
Top speed (km/h):	197	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.5	Energy label:	B
Average consumption (l/100 km):	4.9	NL Tax Rate %:	
Acceleration (s):	9.7	CO2 (g/km):	112
Cargo space (l):	1395	Nb. of Axles:	2
Perm. max weight (kg):	1950	APK date:	11/11/2025

opties

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically adjustable passenger seat |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Inflatable set | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> WiFi | <input checked="" type="checkbox"/> Switch flippers |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> Exterior mirrors with step light | <input checked="" type="checkbox"/> Climate control | <input checked="" type="checkbox"/> Airbag(s) front |
| <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Climate control (digital) | <input checked="" type="checkbox"/> Airbag(s) front + flank |
| <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Large screen navigation | <input checked="" type="checkbox"/> Airbag(s) front + flank + other |
| <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Keyless entry/start/stop | |
| <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Electrically operated rear windows | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/55 R19	Michelin	4
Tire left rear	Summer	Alloy	205/55 R19	Michelin	4
Tire right front	Summer	Alloy	205/55 R19	Michelin	4
Tire right rear	Summer	Alloy	205/55 R19	Michelin	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	(door dealer)	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	07/12/2021	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	26746	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)

Clean outside

🔧 Damages

⊕ Not acceptable



Front right rim - Scratch

🔧 Damages

⊕ Acceptable



Roof - Restyle dent



Rear left rim - Scratch



Front left door - Scratch



Front left screen - Scratch



Front left door - Scratch

🔧 Claimed fields

€ 0

Dak / Restyle Deukje(s) / Vervangen

€ 0

LA velg / Kras(sen) / Polijsten

€ 0

LV portier / Kras(sen) / Bijwerken

€ 0

LV scherm / Kras(sen) / Polijsten

€ 0


RV velg / Kras(sen) / Bijwerken

€ 0

RV portier / Kras(sen) / Bijwerken

€ 0

⚙️ Extra options





AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE