Inspected by: Herman ATS ATS



Brand:	Seat	Mileage(km):	67546
Model:	Ateca	Number of doors:	5
Model type:	1.4 150PK Style Aut.	Vehicle length (cm):	
License plate:	538355	Vehicle width (cm):	
Report code:	8355	Vehicle height (cm):	
Chassis number:	VSSZZZ5FZJ6538355	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	22/01/2018	Power(kw):	110
First NL reg.:		Transmission	Automatic
Color:	Silver V Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1400
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km): Cons. outside the city (l/100 km):		EU category:	
		Energy label:	
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (q/km):	
Cargo space (I):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

📽 opties

<u> </u>	Alloy wheels Licht Sensor ABS Power steering Multifunctional steering wheel
2222	Licht Sensor ABS Power steering Multifunctional steering wheel Remote central locking
	Metallic finish
	LED headlights LED rear lights
Š	Exterior mirrors in car body color
Ť.	Rain sensor
~	Rear wiper

	Rear view camera
\checkmark	Rear parking sensors
	Luggage cover
	Inflatable set
~	USB connection
~	Bluetooth streaming
\checkmark	Bluetooth car kit
\checkmark	Radio
~	Cruise control
$\overline{}$	Climate control (digital)
$\overline{}$	Large screen navigation
~	Electrically operated rear windows

Electrically operated front windows Electrically folding mirrors Electrically adjustable mirrors Central armrest front Audio control on the steering wheel Leather steering wheel Switch flippers Airbag(s) front Airbag(s) front + flank Airbag(s) front + flank + other

¢°	Tires	

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	All weather	Alloy	215/55 R17	Goodyear	4
Tire left rear	All weather	Alloy	215/55 R17	Goodyear	5
Tire right front	All weather	Alloy	215/55 R17	Goodyear	4
Tire right rear	All weather	Alloy	215/55 R17	Goodyear	5

Additional information

No. of keys:	1 🗌 Luxury key	Instruction booklet	Airco works
Interior color:	Anthracite	Maintenance booklet:	Odorless
Upholstery:	Stof		Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	Display ok
No. of headrests:	5	Last turn mileage(km):	Vehicle special usage (None)

▲ Cleaning

Clean inside (Interior is clean)

Clean outside



Acceptable 🔑 Damages Front bumper - Scratch € 0 Voorbumper / Kras(sen) / Bijwerken Buitenspiegel rechts / Kras(sen) / Bijwerken € 0

\$ Extra options



























AUTOFACTOR SOFTWARE FOR AUTOMOTIVE