



Brand:	Volkswagen	Mileage(km):	57286
Model:	T-Cross	Number of doors:	5
Model type:	1.0 TSI 110PK United	Vehicle length (cm):	
License plate:	145692	Vehicle width (cm):	
Report code:	5692	Vehicle height (cm):	
Chassis number:	WVGZZC1ZLY145692	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	28/08/2020	Power(kw):	85
First NL reg.:		Transmission	Manual
Color:	Anthracite <input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(ka):		Displacement(cc):	999
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (black)
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Inflatable set
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (digital)
- Climate control (L/R separated)
- Large screen navigation
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Audio control on the steering wheel
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/60 R16	Continental	3
Tire left rear	Winter	Alloy	205/60 R16	Continental	5
Tire right front	Winter	Alloy	205/60 R16	Continental	3
Tire right rear	Winter	Alloy	205/60 R16	Continental	5

Additional information

No. of keys:	2 <input type="checkbox"/> Luxury key <input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof	<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5 Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5 Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable



Rear bumper - Ontzet

🔧 Damages

⊕ Acceptable



Rear bumper - Scratch



Front left door - Scratch



Front bumper - Scratch



Front right rim - Scratch



Rear right door - Scratch

🏠 Claimed fields

€ 0

Achterbumper / Kras(sen) /

€ 0

Achterbumper / Ontzet / Vervangen

€ 0

LV portier / Kras(sen) /

€ 0

Voorbumper / Kras(sen) /

€ 0

RV velg / Kras(sen) /

€ 0

RA portier / Kras(sen) / Polijsten

€ 0

⚙️ Extra options





