Inspected by: Herman ATS ATS



| Brand: | Peugeot | Mileage(km): | 69163 |
|------------------------------------|------------------------------------|----------------------|------------|
| Model: | 3008 | Number of doors: | 5 |
| Model type: | 1.2 PureTech Blue Lease Premium | Vehicle length (cm): | |
| License plate: | G928LN | Vehicle width (cm): | |
| Report code: | 5962 | Vehicle height (cm): | |
| Chassis number: | VF3MRHNSUKS435962 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front |
| First int. reg.: | 07/11/2019 | Power(kw): | 96 |
| First NL req.: | 07/11/2019 | Transmission | Automatic |
| Color: | Brown Metallic | Number of gears | 8 |
| Weight (kg)(kg): | 1395 | Displacement(cc): | 1199 |
| Empty weight(kg): | 1295 | Number of cylinders: | 3 |
| Wheelbase (cm)(cm): | 268 | Fuel type: | Petrol |
| Top speed (km/h): | 197 | Fuel tank capacity: | |
| Cons. in the city (I/100 km): | 5.6 | EU category: | Euro 6 |
| Cons. outside the city (I/100 km): | 4.5 | Energy label: | В |
| Avarage consumption (I/100 km): | 4.9 | NL Tax Rate %: | |
| Acceleration (s): | 9.7 | CO2 (q/km): | 112 |
| Cargo space (I): | 1395 | Nb. of Axles: | 2 |
| Perm. max weight (kg): | 1950 | APK date: | 28/11/2025 |

opties 🚓

Alloy wheels

Digital dashboard Licht Sensor

ABS

Fog lamps

Power steering

Front seats adjustable in height

Multifunctional steering wheel

Roof rail (silver)

Metallic finish

Panoramic roof (electrical)

LED rear lights

Exterior mirrors in car body color

Exterior mirrors with step light

Privacy glass

Rain sensor

Rear wiper

Rear view camera Rear parking sensors Front parking sensors

Towbar with detachable ball

Rear-seat folding (unequal parts)

1888 Luggage cover

Trunk opens electrically ~

Inflatable set ${f \checkmark}$

 $[\checkmark]$ USB connection

 ${f \checkmark}$ Bluetooth streaming

DAB+

Bluetooth car kit

Radio

~ Cruise control

. Y Y Climate control (digital)

Climate control (L/R separated) Large screen navigation

\ \ \ Keyless entry

Keyless entry/start/stop

 \sim

Electrically operated rear windows ${f \checkmark}$ Electrically operated front windows Electrically folding mirrors

Electrically adjustable mirrors

Electrically adjustable driver's seat (including memory)

Electrically adjustable passenger seat

Electrically heated driver's seat

Electrically heated passenger seat

Central armrest front

Sport seats

Extendable passenger seat

Extendable driver's seat

Adjustable lumbar support driver's seat Adjustable lumbar support passenger seat

7777777 Audio control on the steering wheel

Leather sports steering wheel

Switch flippers

Lane assistance

Pedestrian safety system

Dead angle assistance Airbag(s) front + flank + other

♥ Tires

| Tire | Tire | Wheel | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|--------|-------|------------|-------------|--------------------------|
| position: | type: | type: | | | |
| Tire left front | Winter | Alloy | 205/55 R19 | Michelin | 6 |
| Tire left rear | Winter | Alloy | 205/55 R19 | Michelin | 6 |
| Tire right front | Winter | Alloy | 205/55 R19 | Michelin | 6 |
| Tire right rear | Winter | Alloy | 205/55 R19 | Michelin | 6 |

Additional information No. of keys: Luxury key Instruction booklet Airco works Interior color: Maintenance booklet: Odorless Upholstery: Clean inside (Interior is clean) No. of seats: Stamp date: 5 02/12/2024 Display ok No. of headrests: Last turn mileage(km): 5 69075 Vehicle special usage (None)

Clean outside

کر Damages



Front left rim - Scratch Grille - Break



Not acceptable

Front bumper - Dent



Front right rim - Scratch

Damages

Claimed fields

LV velg / Kras(sen) / Spuiten



Grille / Breuk / Vervangen



Voorbumper / Deuk(en) / Spuiten



Acceptable





♥ Extra options




















































AUTOF CTOR