



Brand:	Hyundai	Mileage(km):	43852
Model:	i20	Number of doors:	5
Model type:	1.0 T-GDI Trend	Vehicle length (cm):	
License plate:	286947	Vehicle width (cm):	
Report code:	6947	Vehicle height (cm):	
Chassis number:	NLHBN51GAPZ286947	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	24/04/2023	Power(kw):	74
First NL reg.:		Transmission:	Manual
Color:	Silver <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):		Displacement(cc):	999
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically heated driver's seat |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically heated passenger seat |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Inflatable set | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunction steering wheel | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Heated steering wheel |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Pedestrian safety system |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Airbag(s) front + flank + other |
| <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Airconditioning | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	195/55 R16	Fulda	9
Tire left rear	All weather	Alloy	195/55 R16	Fulda	7
Tire right front	All weather	Alloy	195/55 R16	Fulda	9
Tire right rear	All weather	Alloy	195/55 R16	Fulda	7

Additional information

No. of keys:	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	29/12/2023	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	23137	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages


⊕ Not acceptable



Roof - Restyle dent



Tailgate/ lid - Dent



Rear bumper - Dent



Front bumper - Scratch



Rear right rim - Scratch

🔧 Damages

🔄 Acceptable



Rear right screen - Restyle dent

🔍 Claimed fields

€ 0

Dak / Restyle Deukje(s) / Restylen

€ 0

Achterklep/deksel / Deuk(en) / Spuiten

€ 0

Achterbumper / Deuk(en) /

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0

RA velg / Kras(sen) / Spuiten

€ 0

RA scherm / Restyle Deukje(s) / Restylen

€ 0

⚙️ Extra options



