



| | | | |
|---|--|-----------------------------|------------|
| Brand: | Renault | Mileage(km): | 63451 |
| Model: | Captur | Number of doors: | 5 |
| Model type: | 1.3 TCe Intens | Vehicle length (cm): | |
| License plate: | G531VZ | Vehicle width (cm): | |
| Report code: | 8371 | Vehicle height (cm): | |
| Chassis number: | VF1R8700064178371 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front |
| First int. reg.: | 20/12/2019 | Power(kw): | 110 |
| First NL reg.: | 20/12/2019 | Transmission: | Automatic |
| Color: | Blue <input checked="" type="checkbox"/> Metallic | Number of gears: | 6 |
| Weight (kg)(ka): | 1343 | Displacement(cc): | 1330 |
| Empty weight(ka): | 1243 | Number of cylinders: | 4 |
| Wheelbase (cm)(cm): | 261 | Fuel type: | Petrol |
| Top speed (km/h): | 210 | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | 6.6 | EU category: | Euro 6 |
| Cons. outside the city (l/100 km): | 4.8 | Energy label: | D |
| Average consumption (l/100 km): | 5.5 | NL Tax Rate %: | |
| Acceleration (s): | 9.5 | CO2 (g/km): | 125 |
| Cargo space (l): | 1343 | Nb. of Axles: | 2 |
| Perm. max weight (kg): | 1746 | APK date: | 20/12/2025 |

opties

- Alloy wheels
- Licht Sensor
- ABS
- Central locking system
- Fog lamps
- Start/stop system
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Metallic finish
- LED headlights
- LED rear lights
- Privacy glass
- Rain sensor
- Rear wiper
- Rear parking sensors
- Towbar with detachable ball
- Rear-seat folding (unequal parts)
- Luggage cover
- Spare wheel (homecomer)
- USB connection
- DAB+
- Bluetooth car kit
- Radio
- WiFi
- Cruise control
- Climate control
- Climate control (digital)
- Large screen navigation
- Keyless entry
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Summer | Alloy | 205/55 R17 | Continental | 2 |
| Tire left rear | Summer | Alloy | 205/55 R17 | Continental | 3 |
| Tire right front | Summer | Alloy | 205/55 R17 | Continental | 2 |
| Tire right rear | Summer | Alloy | 205/55 R17 | Continental | 3 |

Additional information

| | | | | |
|--------------------------|------------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Anthracite | Maintenance booklet: | (door universeel) | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Stof | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 08/12/2023 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 52945 | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable



Roof - Dent

🔧 Damages

⊕ Acceptable



Front left door - Scratch



Front left rim - Weatherworn

📄 Claimed fields

€ 0

Dak / Deuk(en) / Restylen

€ 0

LV portier / Kras(sen) / Bijwerken

€ 0

LV velg / Verweerd / Spuiten

€ 0

⚙️ Extra options



