



<b>Brand:</b>	Peugeot	<b>Mileage(km):</b>	74404
<b>Model:</b>	2008	<b>Number of doors:</b>	5
<b>Model type:</b>	1.2 PureTech Blue Lease Allure	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	G859PJ	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	4379	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VF3CUHNP3KY184379	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	11/11/2019	<b>Power(kw):</b>	81
<b>First NL req.:</b>	11/11/2019	<b>Transmission:</b>	Manual
<b>Color:</b>	Grey <input checked="" type="checkbox"/> Metallic	<b>Number of gears:</b>	6
<b>Weight (kg)(kg):</b>	1236	<b>Displacement(cc):</b>	1199
<b>Empty weight(kg):</b>	1136	<b>Number of cylinders:</b>	3
<b>Wheelbase (cm)(cm):</b>	254	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	191	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	5.9	<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>	4.2	<b>Energy label:</b>	C
<b>Average consumption (l/100 km):</b>	4.8	<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	10.9	<b>CO2 (g/km):</b>	110
<b>Cargo space (l):</b>	1236	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	1655	<b>APK date:</b>	11/11/2025

**opties**

- Alloy wheels
- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Roof rail (silver)
- Metallic finish
- Panoramic roof (fixed)
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Inflatable set
- USB connection
- DAB+
- Bluetooth car kit
- Radio
- WiFi
- Cruise control
- Climate control
- Large screen navigation
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Audio control on the steering wheel
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

**Tires**

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/50 R17	Goodyear	3
Tire left rear	Summer	Alloy	205/50 R17	Goodyear	5
Tire right front	Summer	Alloy	205/50 R17	Goodyear	3
Tire right rear	Summer	Alloy	205/50 R17	Goodyear	5

**Additional information**

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Anthracite	<b>Maintenance booklet:</b>	(door universeel)	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	20/02/2023	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	49926	<input checked="" type="checkbox"/> Vehicle special usage (None)

**Cleaning**

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable

🔧 Damages

⊕ Acceptable



Rear bumper - Scratch



Rear left rim - Weatherworn



Front left rim - Weatherworn



Front right rim - Scratch



Rear right rim - Weatherworn

🔍 Claimed fields

€ 0

Achterbumper / Kras(sen) /

€ 0

LA velg / Verweerd /

€ 0

LV velg / Verweerd /

€ 0

RV velg / Kras(sen) /

€ 0





RA velg / Verweerd /

€ 0

⚙️ Extra options









AUTOFACTOR  
SOFTWARE FOR AUTOMOTIVE