



Brand:	Citroen	Mileage(km):	72182
Model:	C3 Aircross	Number of doors:	5
Model type:	1.2 110PK Shine Aut.	Vehicle length (cm):	
License plate:	039976	Vehicle width (cm):	
Report code:	9976	Vehicle height (cm):	
Chassis number:	VF72RHNPXK4039976	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	28/09/2018	Power(kw):	81
First NL reg.:		Transmission:	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):		Displacement(cc):	1200
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Avarage consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Licht Sensor
- ABS
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Roof rail (black)
- Metallic finish
- Exterior mirrors in car body color
- Exterior mirrors with step light
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Towbar with detachable ball
- Ski hatch
- Luggage cover
- Inflatable set
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Head-up Display
- Climate control (digital)
- Large screen navigation
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Lane assistance
- Pedestrian safety system
- Dead angle assistance
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	215/50 R17	Roadhawk	6
Tire left rear	Summer	Alloy	215/50 R17	Roadhawk	7
Tire right front	Summer	Alloy	215/50 R17	Roadhawk	6
Tire right rear	Summer	Alloy	215/50 R17	Roadhawk	7

Additional information

No. of keys:	1 <input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Brown	Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder		<input checked="" type="checkbox"/> Clean inside (Cleaning)
No. of seats:	5	Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Cleaning)
- Clean outside

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch



Front left door - Restyle dent



Right sill - Scratch



Rear right door - Scratch



Rear bumper - Scratch

🔧 Damages

⊕ Acceptable



Tailgate/ lid - Scratch

🔧 Claimed fields

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0

RV portier / Restyle Deukje(s) / Restylen

€ 0

Dorpel rechts / Kras(sen) / Opvullen

€ 0

RA portier / Kras(sen) / Spuiten

€ 0

Achterbumper / Kras(sen) / Spuiten

€ 0

Achterklep/deksel / Kras(sen) / Polijsten

€ 0

⚙️ Extra options



