



<b>Brand:</b>	Opel	<b>Mileage(km):</b>	60470
<b>Model:</b>	Grandland X	<b>Number of doors:</b>	5
<b>Model type:</b>	1.2 130PK Innovation Aut.	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	294812	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	4812	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	W0VZRHNS0KS294812	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	
<b>First int. reg.:</b>	10/07/2019	<b>Power(kw):</b>	96
<b>First NL req.:</b>		<b>Transmission:</b>	Automatic
<b>Color:</b>	Anthracite <input checked="" type="checkbox"/> Metallic	<b>Number of gears:</b>	
<b>Weight (kg)(kg):</b>		<b>Displacement(cc):</b>	1200
<b>Empty weight(kg):</b>		<b>Number of cylinders:</b>	
<b>Wheelbase (cm)(cm):</b>		<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>		<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>		<b>CO2 (g/km):</b>	
<b>Cargo space (l):</b>		<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>		<b>APK date:</b>	

### opties

- Alloy wheels
- ABS
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Metallic finish
- Halogen headlights
- LED rear lights
- Exterior mirrors in car body color
- Exterior mirrors with step light
- Privacy glass
- Rain sensor
- Rear wiper
- Rear parking sensors
- Front parking sensors
- Towbar with detachable ball
- Rear-seat folding (unequal parts)
- Luggage cover
- Inflatable set
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (L/R separated)
- Large screen navigation
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Adjustable lumbar support driver's seat
- Adjustable lumbar support passenger seat
- Audio control on the steering wheel
- Leather steering wheel
- Heated steering wheel
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

### Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer		225/55 R18	Michelin	3
Tire left rear	Summer		225/55 R18	Michelin	4
Tire right front	Summer		225/55 R18	Michelin	3
Tire right rear	Summer		225/55 R18	Michelin	4

### Additional information

<b>No. of keys:</b>	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Anthracite	<b>Maintenance booklet:</b>		<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>		<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>		<input checked="" type="checkbox"/> Vehicle special usage (None)

### Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable

🔧 Damages

⊕ Acceptable



Rear bumper - Scratch



Rear left rim - Weatherworn



Rear left rim - Weatherworn



Front right rim - Weatherworn



Rear right rim - Weatherworn

🔍 Claimed fields

€  
0

Achterbumper / Kras(sen) / Bijwerken

€  
0

LA velg / Verweerd /

€  
0

LA velg / Verweerd /

€  
0

RV velg / Verweerd /

€  
0

RA velg / Verweerd /

€  
0

⚙️ Extra options





