



Brand:	Renault	Mileage(km):	49447
Model:	Captur	Number of doors:	5
Model type:	0.9 TCe Intens	Vehicle length (cm):	
License plate:	G609PX	Vehicle width (cm):	
Report code:	9011	Vehicle height (cm):	
Chassis number:	VF1R8700864179011	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	13/11/2019	Power(kw):	66
First NL reg.:	13/11/2019	Transmission:	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	5
Weight (kg)(ka):	1248	Displacement(cc):	898
Empty weight(ka):	1148	Number of cylinders:	3
Wheelbase (cm)(cm):	261	Fuel type:	Petrol
Top speed (km/h):	171	Fuel tank capacity:	
Cons. in the city (l/100 km):	6.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.8	Energy label:	D
Average consumption (l/100 km):	5.5	NL Tax Rate %:	
Acceleration (s):	13.1	CO2 (g/km):	125
Cargo space (l):	1248	Nb. of Axles:	2
Perm. max weight (kg):	1676	APK date:	14/08/2025

opties

- Alloy wheels
- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Multifunctional steering wheel
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Inflatable set
- USB connection
- DAB+
- Bluetooth car kit
- WiFi
- Cruise control
- Climate control
- Climate control (digital)
- Large screen navigation
- Keyless entry
- Keyless entry/start/stop
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/55 R17	Goodyear	6
Tire left rear	Summer	Alloy	205/55 R17	Goodyear	5
Tire right front	Summer	Alloy	205/55 R17	Goodyear	6
Tire right rear	Summer	Alloy	205/55 R17	Goodyear	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	(door universeel)	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	24/09/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	47318	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning


- Clean inside (Interior is clean)
- Clean outside

Damages

⊕ Not acceptable



Tailgate/ lid - Dent



Tailgate/ lid - Dent



Rear bumper - Dent



Front left door - Scratch



Front bumper - Scratch

🔧 Damages

🟢 Acceptable



Rear left rim - Scratch



Rear left door - Scratch



Front left door - Scratch



Front left door - Restyle dent



Front bumper - Stone chippings



Front right rim - Scratch



Rear right screen - Scratch

🔪 Claimed fields

Achterklep/deksel / Deuk(en) / Restylen en bijwerken

Achterklep/deksel / Deuk(en) / Restylen en bijwerken

Achterbumper / Deuk(en) / Restylen en bijwerken

LA velg / Kras(sen) / bijwerken

€ 0

€ 0

€
0

LA portier / Kras(sen) / Bijwerken

€
0

LV portier / Kras(sen) / Bijwerken

€
0

LV portier / Kras(sen) / Bijwerken

LV portier / Restyle Deukje(s) / Restylen

€
0

Voorbumper / Steenslag / Bijwerken

€
0

Voorbumper / Kras(sen) / Bijwerken

€
0

RV velg / Kras(sen) / Bijwerken

€
0

RA scherm / Kras(sen) /

€
0

€
0

€
0

€
0

⚙️ Extra options

