



Brand:	Peugeot	Mileage(km):	65661
Model:	3008	Number of doors:	5
Model type:	1.2 130PK Allure Aut. Pano	Vehicle length (cm):	
License plate:	140303	Vehicle width (cm):	
Report code:	0303	Vehicle height (cm):	
Chassis number:	VF3MRHNSULS140303	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	23/06/2020	Power(kw):	96
First NL req.:		Transmission:	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(kg):		Displacement(cc):	1200
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Digital dashboard
- Licht Sensor
- ABS
- Power steering
- Front seats adjustable in height
- Multifunction steering wheel
- Remote central locking
- Roof rail (silver)
- Metallic finish
- Panoramic roof (electrical)
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Exterior mirrors with step light
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Inflatable set
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (digital)
- Climate control (L/R separated)
- Large screen navigation
- Keyless entry/start/stop
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Sport seats
- Adjustable lumbar support driver's seat
- Adjustable adjustable mirrors
- Audio control on the steering wheel
- Leather steering wheel
- Switch flippers
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/55 R18	Bridgestone	5
Tire left rear	Summer	Alloy	225/55 R18	Bridgestone	4
Tire right front	Summer	Alloy	225/55 R18	Bridgestone	5
Tire right rear	Summer	Alloy	225/55 R18	Bridgestone	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	(door dealer)	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	22/12/2023	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	46320	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)

Clean outside

Damages

Not acceptable



Tailgate/ lid - Dent



Rear bumper - Scratch



Rear bumper - Scratch



Rear left screen - Scratch



Rear left door - Scratch



Rear left door - Scratch



Front left door - Scratch



Front left door - Scratch



Front left door - Dent



Front left screen - Scratch



Front bumper - Scratch



Front bumper - Scratch




Right outside mirror - Scratch




Front left door - Scratch



Rear right screen - Dent



Rear right door - Dent



Rear left door - Dent

🔧 Damages

🟢 Acceptable



Tailgate/ lid - Dent



Rear left rim - Scratch



Rear left rim - Scratch



Front left rim - Scratch



Front right rim - Scratch



Rear right door - Scratch



Rear bumper - Scratch

🚩 Claimed fields

€ 0

Achterklep/deksel / Deuk(en) / Restylen

€ 0

LA scherm / Kras(sen) / Polijsten

€ 0

LA portier / Kras(sen) / Polijsten

€ 0

LV scherm / Kras(sen) / Bijwerken

€ 0

Achterklep/deksel / Deuk(en) / Restylen

€ 0

LA velg / Kras(sen) /

€ 0

LV portier / Kras(sen) / Bijwerken

€ 0

LV velg / Kras(sen) /

€ 0

Achterbumper / Kras(sen) / Spuiten

€ 0

LA velg / Kras(sen) /

€ 0

LV portier / Kras(sen) / Bijwerken

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0

Achterbumper / Kras(sen) / Spuiten

€ 0

LA portier / Kras(sen) / Bijwerken

€ 0

LV portier / Deuk(en) / Restylen en bijwerken

€ 0

Voorbumper / Kras(sen) / Bijwerken

€ 0

RV velg / Kras(sen) /

€
0

Buitenspiegel rechts / Kras(sen) /
Polijsten

€
0

RV portier / Kras(sen) / Polijsten

€
0

RA portier / Kras(sen) /

€
0

RA scherm / Deuk(en) / Restylen en
bijwerken

€
0

RA portier / Deuk(en) / Restylen

€
0

Achterbumper / Kras(sen) /

€
0

LA portier / Deuk(en) / Restylen en
bijwerken

€
0

⚙️ Extra options

