



Brand:	Ford	Mileage(km):	41399
Model:	Fiesta	Number of doors:	5
Model type:	1.0 EcoBoost Hybrid Titanium X	Vehicle length (cm):	
License plate:	R212KP	Vehicle width (cm):	
Report code:	6456	Vehicle height (cm):	
Chassis number:	WF0JXXGAHJNP56456	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	04/10/2022	Power(kw):	92
First NL req.:	04/10/2022	Transmission:	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears:	6
Weight (kg)(kg):	1211	Displacement(cc):	999
Empty weight(kg):	1111	Number of cylinders:	3
Wheelbase (cm)(cm):	249	Fuel type:	Petrol
Top speed (km/h):	203	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	B
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):	9.4	CO2 (g/km):	1
Cargo space (l):	1211	Nb. of Axles:	2
Perm. max weight (kg):	1690	APK date:	04/10/2026

opties

- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Multifunctional steering wheel
- Metallic finish
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Inflatable set
- USB connection
- DAB+
- Bluetooth car kit
- Radio
- WiFi
- Cruise control
- Climate control
- Climate control (digital)
- Large screen navigation
- Keyless entry
- Keyless entry/start/stop
- Electrically operated front windows
- Electrically adjustable mirrors
- Electrically adjustable passenger seat
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Extendable passenger seat
- Extendable driver's seat
- Leather steering wheel
- Heated steering wheel
- Lane assistance
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer		195/60 R15	Continental	3
Tire left rear	Summer		195/60 R15	Continental	3
Tire right front	Summer		195/60 R15	Continental	3
Tire right rear	Summer		195/60 R15	Continental	3

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages


⊕ Not acceptable



Rear bumper - Scratch



Front bumper - Scratch



Front bumper - Scratch



Front left door - Scratch



Rear right door - Dent



Rear right side window - Dent



Rear right door - Dent



Rear right screen - Dent

🔧 Damages

⊕ Acceptable



Front left door - Scratch



Front left rim - Scratch



Front right rim - Scratch

👉 Claimed fields

€ 0

Achterbumper / Kras(sen) / Bijwerken

€ 0

LV portier / Kras(sen) /

€ 0

LV velg / Kras(sen) /

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0

RV velg / Kras(sen) /

€ 0

RV portier / Kras(sen) / Polijsten

€ 0

RA portier / Deuk(en) / Spuiten

€ 0

RA zijruit / Deuk(en) / Spotrepair

RA portier / Deuk(en) / Spuiten

RA scherm / Deuk(en) / Spuiten



⚙️ Extra options



