#### Inspected by: Herman ATS ATS



Brand:	Audi	Mileage(km):	8629
Model:	A3 Sportback	Number of doors:	5
Model type:	40 TFSI S-Line Aut.	Vehicle length (cm):	
License plate:	051510	Vehicle width (cm):	
Report code:	1510	Vehicle height (cm):	
Chassis number:	WAUZZZGY3PA051510	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	30/03/2023	Power(kw):	110
First NL reg.:		Transmission	Automatic
Color:	White Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1400
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Hybride (Electro/Benzine) plug-in
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (q/km):	
Cargo space (i):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

#### opties 🚓

- Alloy wheels
- Leather upholstery
- Licht Sensor
- ABS
- Central locking system
- Front seats adjustable in height
- Multifunctional steering wheel Remote central locking
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- SBSSSSSSSSSSSSSS Privacy glass Rain sensor
- Rear wiper
- Rear view camera

- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Charging cable 380V
- Inflatable set ~
- USB connection ~
- Bluetooth streaming
- $\overline{\mathbf{v}}$ Bluetooth car kit
- Radio
- Cruise control
- KKKKK Black top interior
- Climate control (digital) Large screen navigation
- Keyless entry/start/stop
- Audio control on the steering wheel Leather steering wheel
  - Switch flippers
  - Airbag(s) front
  - Airbag(s) front + flank

Central armrest front

Airbag(s) front + flank + other

Electrically operated rear windows

Electrically operated front windows

Electrically folding mirrors

Electrically adjustable mirrors

Electrically heated driver's seat

Electrically heated passenger seat

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	225/45 R17	Bridgestone	7
Tire left rear	Winter	Alloy	225/45 R17	Bridgestone	7
Tire right front	Winter	Alloy	225/45 R17	Bridgestone	7
Tire right rear	Winter	Alloy	225/45 R17	Bridgestone	7

#### **A** Additional information

No. of keys:	1 Luxury key	Instruction booklet	✓ Airco works
Interior color:	Anthracite	Maintenance booklet:	Odorless
Upholstery:	Leder		Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	✓ Display ok
No. of headrests:	5	Last turn mileage(km):	✓ Vehicle special usage (None)

#### **A** Cleaning

- Clean inside (Interior is clean)
- Clean outside

€ 0

### Damages

# Acceptable







Rear bumper - Scratch

Left tailgate - Scratch

Rear left rim - Scratch

## Claimed fields

Achterbumper / Kras(sen) / Bijwerken

Achterlicht links / Kras(sen) / Bijwerken

LA velg / Kras(sen) /







## **☼**<sup>®</sup> <sup>®</sup> Extra options

































AUTOF CTOR