



Brand:	Volkswagen	Mileage(km):	127242
Model:	Golf	Number of doors:	5
Model type:	1.4 TSI Highline Business R	Vehicle length (cm):	
License plate:	K527HJ	Vehicle width (cm):	
Report code:		Vehicle height (cm):	
Chassis number:		Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	04/01/2018	Power(kw):	92
First NL req.:	16/12/2020	Transmission:	Automatic
Color:	Blue <input checked="" type="checkbox"/> Metallic	Number of gears:	7
Weight (kg)(kg):	1291	Displacement(cc):	1395
Empty weight(kg):	1191	Number of cylinders:	4
Wheelbase (cm)(cm):	264	Fuel type:	Petrol
Top speed (km/h):	204	Fuel tank capacity:	
Cons. in the city (l/100 km):	6.4	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.6	Energy label:	C
Average consumption (l/100 km):	5.3	NL Tax Rate %:	
Acceleration (s):	9.1	CO2 (g/km):	121
Cargo space (l):	1291	Nb. of Axles:	2
Perm. max weight (kg):	1800	APK date:	05/01/2026

opties

- Alloy wheels
- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Sports package (exterior)
- Metallic finish
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Rear parking sensors
- Front parking sensors
- Towbar with detachable ball
- Rear-seat folding (unequal parts)
- Ski hatch
- USB connection
- DAB+
- Bluetooth car kit
- Cruise control (adaptive)
- Cruise control
- Sports package (interior)
- Climate control
- Climate control (digital)
- Large screen navigation
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Sport seats
- Extendable passenger seat
- Extendable driver's seat
- Adjustable lumbar support driver's seat
- Adjustable lumbar support passenger seat
- Leather steering wheel
- Pedestrian safety system
- Dead angle assistance
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	225/40 R18	Vredestein	6
Tire left rear	Winter	Alloy	225/40 R18	Vredestein	6
Tire right front	Winter	Alloy	225/40 R18	Vredestein	6
Tire right rear	Winter	Alloy	225/40 R18	Vredestein	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Alcantara			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)

Clean outside

Damages

⊕ Not acceptable



Rear bumper - Scratch



Rear bumper - Scratch



Rear bumper - Scratch



Rear bumper - Scratch



Rear left screen - Scratch



Front left door - Scratch



Front left door - Scratch



Front bumper - Paint repair



Front left door - Scratch

Damages

⊕ Acceptable



Windscreen - Stone chippings



Rear right door - Restyle dent

Claimed fields

€ 0

Achterbumper / Kras(sen) / Bijwerken

€ 0

Achterbumper / Kras(sen) / Polijsten

€ 0

Achterbumper / Kras(sen) / Polijsten

€ 0

Achterbumper / Kras(sen) / Bijwerken

€ 0

LA scherm / Kras(sen) / Polijsten

€ 0

LV portier / Kras(sen) / Polijsten

€ 0

LV portier / Kras(sen) / Polijsten

€ 0

Voorruit / Steenslag /

€ 0

Voorbumper / Lakherstel / Bijwerken

RV portier / Kras(sen) / Bijwerken en polijsten

RA portier / Restyle Deukje(s) /



⚙️ Extra options



