Inspected by: Herman ATS ATS



Brand:	Citroen	Mileage(km):	65025
Model:	C3	Number of doors:	5
Model type:	1.2 82PK Feel	Vehicle length (cm):	
License plate:	624319	Vehicle width (cm):	
Report code:	4319	Vehicle height (cm):	
Chassis number:	VF7SXHMRVLT624319	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	27/11/2020	Power(kw):	60
First NL reg.:		Transmission	Manual
Color:	White Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1200
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (I):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Licht Sensor
- ABS
- Central locking system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking LED headlights
- LED rear lights
- Privacy glass

- Rear wiper
- Rear parking sensors
 - Rear-seat folding (unequal parts)
- Luggage cover USB connection
- ~ Bluetooth car kit
- Radio
- Climate control (digital) Large screen navigation
- Cruise control

- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
 Electrically adjustable mirrors
 Audio control on the steering wheel
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

🗱 Ti	ires

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	All weather		205/55 R16	Continental	5
Tire left rear	All weather		205/55 R16	Michelin	4
Tire right front	All weather		205/55 R16	Continental	5
Tire right rear	All weather		205/55 R16	Continental	4

A Additional information No. of keys: Luxury key Instruction booklet Airco works Interior color: Maintenance booklet: Anthracite (door dealer) Odorless Upholstery: Stof Clean inside (Interior is clean) Stamp date: Display ok No. of seats: 5 No. of headrests: Last turn mileage(km): 5 Vehicle special usage (None)

A Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages



Front left screen - Restyle dent



Front left door - Restyle dent



Front left door - Scratch



Rear right door - Scratch

Damages






Rear left door - Scratch



Front left door - Scratch



Front left screen - Scratch



Bonnet - Stone chippings



Front left side window - Scratch

← Claimed fields

LA portier / Kras(sen) /



RV scherm / Restyle Deukje(s) /



RV zijruit / Kras(sen) /



LV portier / Kras(sen) /



RV portier / Restyle Deukje(s) / Restylen



LV scherm / Kras(sen) /



RV portier / Kras(sen) / Polijsten



Motorkap / Steenslag /



RA portier / Kras(sen) / Bijwerken































