



<b>Brand:</b>	Citroen	<b>Mileage(km):</b>	100790
<b>Model:</b>	Berlingo	<b>Number of doors:</b>	5
<b>Model type:</b>	1.2 110PK Feel	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	509069	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	9069	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VR7ERHNP2LN509069	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	
<b>First int. reg.:</b>	04/03/2020	<b>Power(kw):</b>	81
<b>First NL reg.:</b>		<b>Transmission:</b>	Manual
<b>Color:</b>	Grey <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears:</b>	
<b>Weight (ka)/(kg):</b>		<b>Displacement(cc):</b>	1200
<b>Empty weight(ka):</b>		<b>Number of cylinders:</b>	
<b>Wheelbase (cm)(cm):</b>		<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>		<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>		<b>CO2 (g/km):</b>	
<b>Cargo space (l):</b>		<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>		<b>APK date:</b>	

### opties

- ABS
- Start/stop system
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Metallic finish
- Halogen headlights
- LED rear lights
- Exterior mirrors in car body color
- Removable rear windows
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Aux connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (L/R separated)
- Large screen navigation
- Electrically operated rear windows
- Electrically adjustable mirrors
- Airbag(s) front

### Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer		205/60 R16	Kimi	4
Tire left rear	Summer		205/60 R16	Kimi	4
Tire right front	Summer		205/60 R16	Kimi	4
Tire right rear	Summer		205/60 R16	Kimi	4

### Additional information


<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
<b>Interior color:</b>		<a href="#">Maintenance booklet:</a>	<input checked="" type="checkbox"/> Odorless	
<b>Upholstery:</b>			<input checked="" type="checkbox"/> Clean inside (Interior is clean)	
<b>No. of seats:</b>	5	<a href="#">Stamp date:</a>	<input checked="" type="checkbox"/> Display ok	
<b>No. of headrests:</b>	5	<a href="#">Last turn mileage(km):</a>	<input checked="" type="checkbox"/> Vehicle special usage (None)	

### Cleaning

- Clean inside (Interior is clean)
- Clean outside

### Damages

Not acceptable



Rear left door - Paint repair



Front bumper - Scratch



Rear right screen - Scratch

**Damages**

Acceptable



Front bumper - Paint repair



Front right rim - Scratch



Right A- column - Stone chippings



Rear right rim - Scratch

**Claimed fields**

€ 0

LA portier / Lakherstel / Bijwerken

€ 0

Voorbumper / Kras(sen) / Bijwerken

€ 0

Voorbumper / Lakherstel /

€ 0

RV velg / Kras(sen) /

€ 0

A-Stijl rechts / Steenslag /

€ 0

RA scherm / Kras(sen) / Polijsten

€ 0

RA velg / Kras(sen) /

€ 0

**Extra options**



