



<b>Brand:</b>	Peugeot	<b>Mileage(km):</b>	76623
<b>Model:</b>	2008	<b>Number of doors:</b>	5
<b>Model type:</b>	1.2 110PK Allure Pano	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	034638	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	4638	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VF3CUHNZ6JY034638	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	
<b>First int. reg.:</b>	26/03/2018	<b>Power(kw):</b>	81
<b>First NL reg.:</b>		<b>Transmission:</b>	Manual
<b>Color:</b>	Blue <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears:</b>	
<b>Weight (kg)(ka):</b>		<b>Displacement(cc):</b>	1200
<b>Empty weight(ka):</b>		<b>Number of cylinders:</b>	
<b>Wheelbase (cm)(cm):</b>		<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>		<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	
<b>Avarage consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>		<b>CO2 (g/km):</b>	
<b>Cargo space (l):</b>		<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>		<b>APK date:</b>	

### opties

- Alloy wheels
- ABS
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (silver)
- Metallic finish
- Panoramic roof (fixed)
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Luggage cover
- Aux connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (L/R separated)
- Large screen navigation
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

### Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	195/60 R16	Goodyear	2
Tire left rear	All weather	Alloy	195/60 R16	Goodyear	2
Tire right front	All weather	Alloy	195/60 R16	Goodyear	2
Tire right rear	All weather	Alloy	195/60 R16	Goodyear	2

### Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
<b>Interior color:</b>	Anthracite	<b>Maintenance booklet:</b>	(door dealer)	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	03/06/2024	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	70742	<input checked="" type="checkbox"/> Vehicle special usage (None)

### Cleaning

- Clean inside (Interior is clean)
- Clean outside

### Damages

Not acceptable



Tailgate/ lid - Scratch



Rear left door - Scratch

🔧 Damages

⊕ Acceptable



Front left rim - Scratch




Front right rim - Scratch



Right sill - Scratch



Rear right rim - Scratch



Rear right door - Scratch

👁️ Claimed fields

€ 0

Achterklep/deksel / Kras(sen) / Polijsten

€ 0

LA portier / Kras(sen) / Polijsten

€ 0

LV velg / Kras(sen) /

€ 0

RV velg / Kras(sen) /

€ 0

Dorpel rechts / Kras(sen) /

€ 0

RA velg / Kras(sen) /

€ 0

RA portier / Kras(sen) /

€ 0

⚙️ Extra options



