



<b>Brand:</b>	Renault	<b>Mileage(km):</b>	38830
<b>Model:</b>	Captur	<b>Number of doors:</b>	5
<b>Model type:</b>	1.3 140PK Intens Aut.	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	297111	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	7111	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VF1RJB00566297111	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	
<b>First int. reg.:</b>	08/12/2020	<b>Power(kw):</b>	103
<b>First NL reg.:</b>		<b>Transmission:</b>	Automatic
<b>Color:</b>	White <input checked="" type="checkbox"/> Metallic	<b>Number of gears:</b>	
<b>Weight (kg)(kg):</b>		<b>Displacement(cc):</b>	1300
<b>Empty weight(kg):</b>		<b>Number of cylinders:</b>	
<b>Wheelbase (cm)(cm):</b>		<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>		<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>		<b>CO2 (g/km):</b>	
<b>Cargo space (l):</b>		<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>		<b>APK date:</b>	

### opties

- Alloy wheels
- Licht Sensor
- ABS
- Start/stop system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (silver)
- Metallic finish
- LED headlights
- LED rear lights
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Luggage cover
- Inflatable set
- Aux connection
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (digital)
- Large screen navigation
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically heated windscreen
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Leather steering wheel
- Switch flippers
- Heated steering wheel
- Lane assistance
- Pedestrian safety system
- Airbag(s) front + flank + other

### Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	215/55 R18	Pirelli	4
Tire left rear	All weather	Alloy	215/55 R18	Pirelli	7
Tire right front	All weather	Alloy	215/55 R18	Pirelli	4
Tire right rear	All weather	Alloy	215/55 R18	Pirelli	7

### Additional information

<b>No. of keys:</b>	1 <input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Anthracite	<b>Maintenance booklet:</b>	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Half stof/leder		<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	<input checked="" type="checkbox"/> Vehicle special usage (None)

### Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable



Roof - Dent

🔧 Damages

⊕ Acceptable



Geen Instructie / Servicepas Aanwezig



Rear left screen - Restyle dent

📄 Claimed fields

€ 0

Geen Instructie / Servicepas Aanwezig /

€ 0

Dak / Deuk(en) / Restylen

€ 0

LA scherm / Restyle Deukje(s) / Restylen

€ 0

⚙️ Extra options



