



Brand:	Citroen	Mileage(km):	81414
Model:	C3	Number of doors:	5
Model type:	1.2 PureTech Shine	Vehicle length (cm):	
License plate:	RN517L	Vehicle width (cm):	
Report code:	9101	Vehicle height (cm):	
Chassis number:	VF7SXHMZ6HT689101	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	05/01/2018	Power(kw):	60
First NL reg.:	05/01/2018	Transmission:	Manual
Color:	Green <input type="checkbox"/> Metallic	Number of gears:	5
Weight (kg)(ka):	1055	Displacement(cc):	1199
Empty weight(ka):	955	Number of cylinders:	3
Wheelbase (cm)(cm):	254	Fuel type:	Petrol
Top speed (km/h):	168	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.7	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.1	Energy label:	C
Average consumption (l/100 km):	4.7	NL Tax Rate %:	
Acceleration (s):	14.6	CO2 (g/km):	109
Cargo space (l):	1055	Nb. of Axles:	2
Perm. max weight (kg):	1550	APK date:	05/01/2026

opties

- Alloy wheels
- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Towbar with fixed ball
- Rear-seat folding (equal parts)
- Rear-seat folding (unequal parts)
- Luggage cover
- Jack
- Spare wheel (full)
- USB connection
- DAB+
- Bluetooth car kit
- Radio
- WiFi
- Cruise control
- Climate control
- Climate control (analog)
- Large screen navigation
- Electrically operated rear windows
- Electrically operated front windows
- Electrically adjustable mirrors
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Lane assistance
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/50 R17	Goodyear	4
Tire left rear	Summer	Alloy	205/50 R17	Goodyear	6
Tire right front	Summer	Alloy	205/50 R17	Goodyear	4
Tire right rear	Summer	Alloy	205/50 R17	Goodyear	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	15/03/2023	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	61793	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages

⊕ Not acceptable

🔧 Damages

⊕ Acceptable



Front left door - Scratch



Tailgate/ lid - Restyle dent



Front left door - Restyle dent

👉 Claimed fields

€ 0

RV portier / Kras(sen) / Polijsten

€ 0

Achterklep/deksel / Restyle Deukje(s) / Restylen

€ 0

LV portier / Restyle Deukje(s) / Restylen

€ 0

⚙️ Extra options



