



Brand:	Citroen	Mileage(km):	37382
Model:	C3 Aircross	Number of doors:	5
Model type:	1.2 130PK Shine Aut. Pano	Vehicle length (cm):	
License plate:	016522	Vehicle width (cm):	
Report code:	6522	Vehicle height (cm):	
Chassis number:	VF72RHNS1P4016522	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	31/03/2023	Power(kw):	96
First NL req.:		Transmission:	Automatic
Color:	Red <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(kg):		Displacement(cc):	1200
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Roof rail (black)
- Metallic finish
- Panoramic roof (electrical)
- LED headlights
- LED rear lights
- Exterior mirrors with step light
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- USB connection
- DAB+
- Bluetooth car kit
- Cruise control
- Head-up Display
- Climate control (digital)
- Large screen navigation
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Lane assistance
- Pedestrian safety system
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/60 R16	Bridgestone	4
Tire left rear	Summer	Alloy	205/60 R16	Bridgestone	6
Tire right front	Summer	Alloy	205/60 R16	Bridgestone	4
Tire right rear	Summer	Alloy	205/60 R16	Bridgestone	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	20/12/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	37376	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

6 Damages



Rear bumper - Scratch



Rear bumper - Dent



Front left door - Restyle dent

🔧 Damages

⊕ Acceptable



Rear right screen - Scratch

📄 Claimed fields

€ 0

RA scherm / Kras(sen) / Bijwerken

€ 0

Achterbumper / Kras(sen) / Bijwerken

€ 0

Achterbumper / Deuk(en) / Spotrepair

€ 0

LV portier / Restyle Deukje(s) / Restylen en bijwerken

€ 0

⚙️ Extra options



