Inspected by: Herman ATS ATS



Brand:	Seat	Mileage(km):	60389
Model:	Arona	Number of doors:	5
Model type:	1.0 110PK FR Aut.	Vehicle length (cm):	
License plate:	068879	Vehicle width (cm):	
Report code:	8879	Vehicle height (cm):	
Chassis number:	VSSZZZKJZMR068879	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	20/04/2021	Power(kw):	81
First NL reg.:		Transmission	Automatic
Color:	White Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	999
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	
Cons. outside the city (I/100 km): Avarage consumption (I/100 km):		Energy label: NL Tax Rate %:	
Avarage consumption (I/100 km):		NL Tax Rate %:	2

opties

- Alloy wheels
- Licht Sensor
- ABS
- Fog lamps
- Start/stop system Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- SOSSSSSSSSSSSSS Remote central locking
- Roof rail (silver)
- LED headlights
- LED rear lights
- Privacy glass Rain sensor

- Rear wiper
- Rear view camera
- Automatic parking system
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- \ \ \ Luggage cover
- ~ Inflatable set
- $\overline{\mathbf{v}}$ USB connection
- DAB+
- Bluetooth car kit
- Cruise control
- SISIS Sports package (interior)
 - Black top interior

- Climate control (L/R separated)
- Electrically operated rear windows
- Electrically operated front windows

- Electrically heated driver's seat Electrically heated passenger seat
- Audio control on the steering wheel
- Climate control (L/R separated Large screen navigation Electrically operated rear wind Electrically operated front wind Electrically folding mirrors Electrically adjustable mirrors Electrically heated driver's seat Electrically heated driver's seat Central armrest front Audio control on the steering w Leather sports steering wheel Switch flippers Pedestrian safety system Airbag(s) front + flank + other

O.C.	Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/55 R17	Continental	6
Tire left rear	Winter	Alloy	205/55 R17	Continental	8
Tire right front	Winter	Alloy	205/55 R17	Continental	6
Tire right reer	Mintor	Alless	20E/EE D17	Continental	0

Additional information

- / taartional illioniation				
No. of keys:	2 Luxury key	Instruction booklet		Airco works
Interior color:	Anthracite	Maintenance booklet:		✓ Odorless
Upholstery:	Stof			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	23/02/2024	Display ok
No. of headrests:	5	Last turn mileage(km):	47889	✓ Vehicle special usage (None)

A Cleaning

- Clean inside (Interior is clean)
- Clean outside (None)

Damages





Auto Vuil En Bevroren



Tailgate/ lid - Restyle dent

₹ Claimed fields

Auto Vuil En Bevroren /

Achterklep/deksel / Restyle Deukje(s) / Restylen





☼Extra options



















€











AUTOF CTOR