



Brand:	Volvo	Mileage(km):	41601
Model:	XC40	Number of doors:	5
Model type:	T5 PHEV Inscription Aut.	Vehicle length (cm):	
License plate:	696194	Vehicle width (cm):	
Report code:	6194	Vehicle height (cm):	
Chassis number:	YV1XZBBVFN2696194	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	28/10/2021	Power(kw):	132
First NL reg.:		Transmission:	Automatic
Color:	Blue <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):		Displacement(cc):	1500
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Hybride (Electro/Benzine) plug-in
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Leather upholstery
- Digital dashboard
- Licht Sensor
- ABS
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (silver)
- Metallic finish
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Rain sensor
- Rear wiper
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Trunk opens electrically
- Charging cable 380V
- Charging cable 220V
- Inflatable set
- USB connection
- DAB+
- Bluetooth car kit
- Cruise control
- Black top interior
- Climate control (L/R separated)
- Large screen navigation
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Sport seats
- Extendable passenger seat
- Extendable driver's seat
- Adjustable lumbar support driver's seat
- Adjustable lumbar support passenger seat
- Audio control on the steering wheel
- Leather steering wheel
- Pedestrian safety system
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	235/50 R19	Momo	7
Tire left rear	Summer	Alloy	235/50 R19	Continental	5
Tire right front	Summer	Alloy	235/50 R19	Momo	7
Tire right rear	Summer	Alloy	235/50 R19	Continental	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Beige	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	0	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)

Clean outside

🔧 Damages

⊕ Not acceptable



Front bumper - Dent



Front bumper - Scratch



Front bumper - Ontzet



Front bumper - Scratch



Front bumper - Dent



Front left door - Scratch



Rear right door - Dent



Rear right screen - Scratch



Rear bumper - Scratch



Rear bumper - Scratch



Front left door - Restyle dent

🔧 Damages


⊕ Acceptable



Windscreen - Scratch



Tailgate/ lid - Scratch



Rear left screen - Scratch



Rear left rim - Scratch

Claimed fields

€ 0

Voorruit / Kras(sen) / Bijwerken

€ 0

Voorbumper / Deuk(en) / Spuiten

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0

Voorbumper / Ontzet / Vervangen

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0

Voorbumper / Deuk(en) / Spuiten

€ 0

RV portier / Kras(sen) / Spuiten

€ 0

RA portier / Deuk(en) /

€ 0

RA scherm / Kras(sen) / Bijwerken

€ 0

Achterbumper / Kras(sen) / Bijwerken

€ 0

Achterbumper / Kras(sen) / Bijwerken

€ 0

Achterklep/deksel / Kras(sen) / Polijsten

€ 0

LA scherm / Kras(sen) / Polijsten

€ 0

LA velg / Kras(sen) / Zo laten

€ 0

LV portier / Restyle Deukje(s) / Restylen en bijwerken

€ 0

Extra options



