



Brand:	Citroen	Mileage(km):	19652
Model:	C3	Number of doors:	5
Model type:	1.2 82PK Shine Pack 17"	Vehicle length (cm):	
License plate:	630339	Vehicle width (cm):	
Report code:	0339	Vehicle height (cm):	
Chassis number:	VF7SXHMRVMT630339	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	08/10/2021	Power(kw):	60
First NL reg.:		Transmission	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(ka):		Displacement(cc):	999
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Avarage consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Licht Sensor
- ABS
- Central locking system
- Fog lamps
- Power steering
- Multifunctional steering wheel
- Metallic finish
- LED headlights
- LED rear lights
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- USB connection
- Bluetooth streaming
- DAB+
- Bluetooth car kit
- Cruise control
- Climate control (digital)
- Large screen navigation
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Pedestrian safety system
- Dead angle assistance
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/50 R17	Goodyear	6
Tire left rear	Summer	Alloy	205/50 R17	Goodyear	8
Tire right front	Summer	Alloy	205/50 R17	Goodyear	6
Tire right rear	Summer	Alloy	205/50 R17	Goodyear	8

Additional information

No. of keys:	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages

⊕ Not acceptable



Roof - Restyle dent



Left B- column - Restyle dent

🔧 Damages

📌 Acceptable



Compressorset Manco



Boekjes Manco

📍 Claimed fields

€ 0

Compressorset Manco /

€ 0

Boekjes Manco /

€ 0

Dak / Restyle Deukje(s) / Restylen

€ 0

B-Stijl links / Restyle Deukje(s) / Restylen

€ 0

⚙️ Extra options



