



Brand:	Toyota	Mileage(km):	75194
Model:	Corolla Touring Sport	Number of doors:	5
Model type:	1.8 Hybrid Premium Plus Aut. Leder	Vehicle length (cm):	
License plate:	143623	Vehicle width (cm):	
Report code:	3623	Vehicle height (cm):	
Chassis number:	SB1Z93BE50E143623	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	08/10/2020	Power(kw):	72
First NL req.:		Transmission:	Automatic
Color:	Silver <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(kg):		Displacement(cc):	1800
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Hybride (Electro/Benzine) non plug-in
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Leather upholstery
- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Sports package (exterior)
- Roof rail (silver)
- Metallic finish
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Automatic parking system
- Rear parking sensors
- Front parking sensors
- Luggage cover
- Trunk opens electrically
- Inflatable set
- USB connection
- Bluetooth streaming
- DAB+
- Bluetooth car kit
- Cruise control (adaptive)
- Sports package (interior)
- Black top interior
- Climate control (L/R separated)
- Large screen navigation
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Sport seats
- Adjustable lumbar support driver's seat
- Audio control on the steering wheel
- Leather steering wheel
- Pedestrian safety system
- Dead angle assistance
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	225/45 R17	Continental	7
Tire left rear	Winter	Alloy	225/45 R17	Continental	6
Tire right front	Winter	Alloy	225/45 R17	Continental	7
Tire right rear	Winter	Alloy	225/45 R17	Continental	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	18/09/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	67803	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

Clean inside (Interior is clean)

Clean outside

Damages

Not acceptable



Rear left screen - Dent




Left sill - Scratch



lichte slijtplek stoel linksvoor

Damages

Acceptable



Front bumper - Scratch



Rear right screen - Restyle dent

Claimed fields

€
0

Voorbumper / Kras(sen) / Spuiten

€
0

RA scherm / Restyle Deukje(s) / Restylen

€
0





LA scherm / Deuk(en) / Spuiten

€
0

Dorpel links / Kras(sen) / Spuiten

€
0

Extra options





AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE