



Brand:	Renault	Mileage(km):	58657
Model:	Captur	Number of doors:	5
Model type:	1.3 130PK Intens Aut. Pano 18"	Vehicle length (cm):	
License plate:	009839	Vehicle width (cm):	
Report code:	9839	Vehicle height (cm):	
Chassis number:	VF1RJB00065009839	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	17/02/2020	Power(kw):	96
First NL req.:		Transmission:	Automatic
Color:	Orange <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(kg):		Displacement(cc):	1300
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Licht Sensor
- ABS
- Start/stop system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Metallic finish
- Sliding / tilting roof (electric)
- LED headlights
- LED rear lights
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Towbar with detachable ball
- Rear-seat folding (unequal parts)
- Luggage cover
- Spare wheel (homecomer)
- Aux connection
- USB connection
- Bluetooth streaming
- DAB+
- Bluetooth car kit
- Cruise control
- Climate control
- Large screen navigation
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Leather steering wheel
- Switch flippers
- Lane assistance
- Pedestrian safety system
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	215/55 R18	Firestone	2
Tire left rear	Summer	Alloy	215/55 R18	Firestone	6
Tire right front	Summer	Alloy	215/55 R18	Firestone	2
Tire right rear	Summer	Alloy	215/55 R18	Firestone	6

Additional information

No. of keys:	1 <input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof		<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable



Bonnet - Scratch




Front bumper - Scratch



Front bumper - Scratch



Front bumper - Scratch



Right outside mirror - Scratch



Rear right door - Restyle dent



Rear right door - Restyle dent




Rear right rim - Scratch



Rear bumper - Dent



Rear left door - Restyle dent



Rear left door - Restyle dent

🔧 Damages

⊕ Acceptable



Front left door - Restyle dent

🔪 Claimed fields

€
0

Motorkap / Kras(sen) / Polijsten

Voorbumper / Kras(sen) / Spuiten

Voorbumper / Kras(sen) / Spuiten

Voorbumper / Kras(sen) / Bijwerken

€
0

Buitenspiegel rechts / Kras(sen) / Spuiten

€
0

Achterbumper / Deuk(en) / Spuiten

€
0

€
0

RA portier / Restyle Deukje(s) / Restylen en bijwerken

€
0

LA portier / Restyle Deukje(s) / Restylen en bijwerken

€
0

€
0

RA portier / Restyle Deukje(s) / Restylen

€
0

LV portier / Restyle Deukje(s) / Restylen

€
0

€
0

RA velg / Kras(sen) / Spuiten

€
0

LA portier / Restyle Deukje(s) / Restylen en bijwerken

€
0

⚙️ Extra options



