



Brand:	Seat	Mileage(km):	66196
Model:	Leon	Number of doors:	5
Model type:	1.5 TSI FR	Vehicle length (cm):	
License plate:	K963RK	Vehicle width (cm):	
Report code:	0274	Vehicle height (cm):	
Chassis number:	VSSZZKLZMR060274	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	12/02/2021	Power(kw):	110
First NL reg.:	12/02/2021	Transmission:	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears:	6
Weight (kg)(ka):	1374	Displacement(cc):	1498
Empty weight(ka):	1274	Number of cylinders:	4
Wheelbase (cm)(cm):	269	Fuel type:	Petrol
Top speed (km/h):	221	Fuel tank capacity:	
Cons. in the city (l/100 km):	6.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.5	Energy label:	B
Average consumption (l/100 km):	5.3	NL Tax Rate %:	
Acceleration (s):	8.7	CO2 (g/km):	121
Cargo space (l):	1374	Nb. of Axles:	2
Perm. max weight (kg):	1960	APK date:	12/02/2025

opties

- Alloy wheels
- Digital dashboard
- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Sports package (exterior)
- Roof rail (black)
- Metallic finish
- LED headlights
- LED rear lights
- Privacy glass
- Rain sensor
- Rear wiper
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Inflatable set
- USB connection
- DAB+
- Bluetooth car kit
- Radio
- Cruise control
- Sports package (interior)
- Black top interior
- Airconditioning in the back
- Climate control
- Climate control (digital)
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Adjustable lumbar support driver's seat
- Adjustable lumbar support passenger seat
- Audio control on the steering wheel
- Leather sports steering wheel
- Pedestrian safety system
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/40 R18	Goodyear	7
Tire left rear	Summer	Alloy	225/40 R18	Bridgestone	6
Tire right front	Summer	Alloy	225/40 R18	Goodyear	7
Tire right rear	Summer	Alloy	225/40 R18	Bridgestone	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	15/02/2023	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	30625	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable



Front left rim - Scratch



Front right rim - Scratch



Tailgate/ lid - Dent

🔧 Damages

⊕ Acceptable



Front bumper - Dent



Front left door - Restyle dent



Rear right rim - Scratch



Rear bumper - Scratch



Rear left screen - Restyle dent

👉 Claimed fields

€ 0

LV velg / Kras(sen) / Spuiten

€ 0

Voorbumper / Deuk(en) / Zo laten

€ 0

RV velg / Kras(sen) / Spuiten

€ 0

RV portier / Restyle Deukje(s) / Restylen

€ 0

RA velg / Kras(sen) / Zo laten

€ 0

Achterklep/deksel / Deuk(en) / Spuiten

€ 0

Achterbumper / Kras(sen) / Bijwerken

€ 0

LA scherm / Restyle Deukje(s) / Restylen

€ 0

⚙️ Extra options





AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE