



Brand:	Citroen	Mileage(km):	45833
Model:	C3	Number of doors:	5
Model type:	1.2 82PK Shine	Vehicle length (cm):	
License plate:	528016	Vehicle width (cm):	
Report code:	8016	Vehicle height (cm):	
Chassis number:	VF7SXHMRVNT528016	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	13/03/2022	Power(kw):	61
First NL reg.:		Transmission:	Manual
Color:	White <input type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):		Displacement(cc):	1200
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Licht Sensor
- ABS
- Multifunctional steering wheel
- Remote central locking
- LED headlights
- LED rear lights
- Rear wiper
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Inflatable set
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (digital)
- Large screen navigation
- Electrically operated rear windows
- Electrically adjustable mirrors
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer		205/55 R16	Michelin	3
Tire left rear	Summer		205/55 R16	Michelin	4
Tire right front	Summer		205/55 R16	Michelin	3
Tire right rear	Summer		205/55 R16	Michelin	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	(door dealer)	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	20/03/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	34434	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages

Not acceptable

Damages

Acceptable



Front bumper - Stone chippings

Claimed fields

€ 0

Voorbumper / Steenslag / Bijwerken

€ 0

Extra options



