



<b>Brand:</b>	Skoda	<b>Mileage(km):</b>	87798
<b>Model:</b>	Karoq	<b>Number of doors:</b>	5
<b>Model type:</b>	1.5 150PK Business Ed. Aut.	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	026283	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	6283	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	TMBJR7NU0N5026283	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	
<b>First int. reg.:</b>	29/12/2021	<b>Power(kw):</b>	110
<b>First NL req.:</b>		<b>Transmission:</b>	Automatic
<b>Color:</b>	Black <input checked="" type="checkbox"/> Metallic	<b>Number of gears:</b>	
<b>Weight (kg)(kg):</b>		<b>Displacement(cc):</b>	1500
<b>Empty weight(kg):</b>		<b>Number of cylinders:</b>	
<b>Wheelbase (cm)(cm):</b>		<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>		<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>		<b>CO2 (g/km):</b>	
<b>Cargo space (l):</b>		<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>		<b>APK date:</b>	

### opties

- Alloy wheels
- ABS
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (black)
- Metallic finish
- Halogen headlights
- LED rear lights
- Exterior mirrors in car body color
- Exterior mirrors with step light
- Rear view camera
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Trunk opens electrically
- Inflatable set
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (L/R separated)
- Large screen navigation
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Adjustable lumbar support driver's seat
- Adjustable lumbar support passenger seat
- Audio control on the steering wheel
- Leather steering wheel
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

### Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	215/55 R17	Michelin	6
Tire left rear	Winter	Alloy	215/55 R17	Michelin	6
Tire right front	Winter	Alloy	215/55 R17	Michelin	6
Tire right rear	Winter	Alloy	215/55 R17	Michelin	6

### Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Aircro works
<b>Interior color:</b>	Anthracite	<b>Maintenance booklet:</b>	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>		<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>		<input checked="" type="checkbox"/> Vehicle special usage (None)

### Cleaning

- Clean inside (Interior is clean)
- Clean outside


6 Damages



Rear bumper - Scratch



Rear bumper - Scratch



Left outside mirror - Scratch



Front left rim - Scratch



Front bumper - Paint repair



Front left door - Scratch



Rear right door - Paint repair



Rear right screen - Paint repair



Roof - Restyle dent



Roof - Hail damage

🔧 Damages

⊕ Acceptable



Rear left door - Scratch



Front left door - Scratch

🏠 Claimed fields

€ 0

Achterbumper / Kras(sen) / Bijwerken

€ 0

Achterbumper / Kras(sen) / Bijwerken

€ 0

LA portier / Kras(sen) /

€ 0

LV portier / Kras(sen) /

€ 0

Buitenspiegel links / Kras(sen) / Bijwerken

€ 0

LV velg / Kras(sen) / Bijwerken

€ 0

Voorbumper / Lakherstel / Bijwerken

€ 0

RV portier / Kras(sen) / Bijwerken

€ 0

RA portier / Lakherstel / Bijwerken en polijsten

€ 0

RA scherm / Lakherstel / Bijwerken en polijsten

€ 0

Dak / Restyle Deukje(s) / Restylen

€ 0

Dak / Hagelschade / Restylen

€ 0

⚙️ Extra options

