



Brand:	Audi	Mileage(km):	60481
Model:	A1 Sportback	Number of doors:	5
Model type:	25 TFSI Pro Line	Vehicle length (cm):	
License plate:	K685TK	Vehicle width (cm):	
Report code:	5736	Vehicle height (cm):	
Chassis number:	WAUZZZGB3MR035736	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	04/03/2021	Power(kw):	70
First NL reg.:	04/03/2021	Transmission:	Manual
Color:	White <input type="checkbox"/> Metallic	Number of gears:	5
Weight (kg)(ka):	1175	Displacement(cc):	999
Empty weight(ka):	1075	Number of cylinders:	3
Wheelbase (cm)(cm):	256	Fuel type:	Petrol
Top speed (km/h):	193	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.7	EU category:	Euro 6
Cons. outside the city (l/100 km):	4	Energy label:	B
Average consumption (l/100 km):	4.7	NL Tax Rate %:	
Acceleration (s):	11	CO2 (g/km):	107
Cargo space (l):	1175	Nb. of Axles:	2
Perm. max weight (kg):	1630	APK date:	04/03/2025

opties

- Alloy wheels
- Licht Sensor
- ABS
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Halogen headlights
- LED rear lights
- Exterior mirrors in car body color
- Rain sensor
- Rear wiper
- Rear-seat folding (equal parts)
- Rear-seat folding (unequal parts)
- Luggage cover
- USB connection
- DAB+
- Bluetooth car kit
- Radio
- WiFi
- Cruise control
- Airconditioning
- Electrically operated rear windows
- Electrically operated front windows
- Electrically adjustable mirrors
- Central armrest front
- Leather sports steering wheel
- Leather steering wheel
- Lane assistance
- Pedestrian safety system
- Airbag(s) front
- Airbag(s) front + flank

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	185/65 R15	Continental	5
Tire left rear	Summer	Alloy	185/65 R15	Continental	5
Tire right front	Summer	Alloy	185/65 R15	Continental	5
Tire right rear	Summer	Alloy	185/65 R15	Continental	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning


- Clean inside (Interior is clean)
- Clean outside

Damages

⊗ Not acceptable



Roof - Dent



Roof - Dent



Front bumper - Ontzet



Front bumper - Dent



Front bumper - Scratch

🔧 Damages

🔄 Acceptable



Front bumper - Break



Front bumper - Dent

👉 Claimed fields

€ 0

Dak / Deuk(en) / Restylen en bijwerken

€ 0

Dak / Deuk(en) / Restylen en bijwerken

€ 0

Voorbumper / Ontzet / Zo laten

€ 0

Voorbumper / Deuk(en) /

€ 0

Voorbumper / Breuk /

€ 0

Voorbumper / Deuk(en) /

€ 0

Voorbumper / Kras(sen) / Bijwerken

€ 0

⚙️ Extra options



