

Brand:	Volkswagen	Mileage(km):
Model:	Tiguan	Number of doors:
Model type:	1.4 TSI 4Motion Highline Aut. Pano	Vehicle length (cm):
License plate:	N706HG	Vehicle width (cm):
Report code:	6723	Vehicle height (cm):
Chassis number:	WVGZZZ5NZJW946723	Vehicle body type:
Type of vehicle:	Luxury	Traction:
First int. reg.:	28/05/2018	Power(kw):
First NL req.:	16/11/2021	Transmission
Color:	Grey 🗹 Metallic	Number of gears
Weight (kg)(kg):	1592	Displacement(cc):
Empty weight(kg):	1492	Number of cylinders:
Wheelbase (cm)(cm):	268	Fuel type:
Top speed (km/h):	200	Fuel tank capacity:
Cons. in the city (I/100 km):	8.1	EU category:
Cons. outside the city (I/100 km):	6.1	Energy label:
Avarage consumption (I/100 km):	6.9	NL Tax Rate %:
Acceleration (s):	9.2	CO2 (q/km):
Cargo space (I):	1592	Nb. of Axles:
Perm. max weight (kg):	2150	APK date:

Inspected by: Herman ATS ATS

	Mileage(km):	136925
	Number of doors:	5
9	Vehicle length (cm):	
	Vehicle width (cm):	
	Vehicle height (cm):	
	Vehicle body type:	
	Traction:	Front+Rear
	Power(kw):	110
	Transmission	Automatic
	Number of gears	
	Displacement(cc):	1395
	Number of cylinders:	4
	Fuel type:	Petrol
	Fuel tank capacity:	
	EU category:	Euro 6
	Energy label:	E
	NL Tax Rate %:	
	CO2 (q/km):	155
	Nb. of Axles:	2
	APK date:	28/05/2026

opties

\checkmark	Alloy wheels
$\overline{}$	Leather upholstery
~	ABS
<u>3888888888888888888888888888888888888</u>	Fog lamps
$\overline{}$	Power steering
$\overline{}$	Front seats adjustable in height
$\overline{}$	Multifunctional steering wheel
~	Remote central locking
~	Roof rail (silver)
$\overline{}$	Metallic finish
$\overline{}$	Panoramic roof (electrical)
$\overline{}$	LED headlights
$\overline{}$	LED headlights (adaptive)
$\overline{}$	Headlight washers
$\overline{}$	LED rear lights
$\overline{}$	Exterior mirrors with step light
$\overline{}$	Privacy glass
$\overline{}$	Rain sensor
~	360 ° camera system
~	Rear parking sensors

_	E 1 11
\checkmark	Front parking sensors
\sim	Rear-seat folding (equal parts)
$\overline{}$	Rear-seat folding (unequal parts)
$\overline{}$	Luggage cover
$\overline{}$	Trunk opens electrically
$\overline{}$	Inflatable set
$\overline{}$	USB connection
	Radio/CD player
\checkmark	Bluetooth car kit
\sim	Cruise control (adaptive)
\sim	Cruise control
\sim	Airconditioning in the back
$\overline{}$	Climate control
$\overline{}$	Climate control (digital)
$\overline{}$	Climate control (L/R separated)
$\overline{}$	Large screen navigation
~	Keyless entry
<u> </u>	Keyless entry/start/stop
	Electrically operated rear windows
~	Electrically operated front windows

¢; Tires					
Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	235/55 R18	Continental	4
Tire left rear	Summer	Alloy	235/55 R18	Continental	3
Tire right front	Summer	Alloy	235/55 R18	Continental	4
Tire right rear	Summer	Alloy	235/55 R18	Continental	3

Additional information

No. of keys:	2 🗌 Luxury key	Instruction booklet		Airco works
Interior color:	Black	Maintenance booklet:	(door universeel)	Odorless
Upholstery:	Leder			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	10/09/2024	💟 Display ok
No. of headrests:	5	Last turn mileage(km):	128124	Vehicle special usage (None)

Cleaning

Clean inside (Interior is clean)

Clean outside

Not acceptable Damages AND DESCRIPTION OF THE OWNER OWNER Tailgate/ lid - Restyle dent Right tailgate - Break Rear bumper - Scratch Rear bumper - Scratch Front left door - Restyle dent Front left screen - Scratch Front left door - Scratch Rear right screen - Scratch Acceptable 🖉 Damages 0

Achterklep/deksel / Restyle Deukje(s) / Restylen

LV portier / Restyle Deukje(s) / Restylen



Achterlicht rechts / Breuk / Vervangen

LV scherm / Kras(sen) / Zo laten

Achterbumper / Kras(sen) / Bijwerken

RV portier / Kras(sen) / Polijsten



Achterbumper / Kras(sen) / Bijwerken



\$ Extra options

































