



Brand:	Opel	Mileage(km):	68719
Model:	Grandland X	Number of doors:	5
Model type:	1.2 130PK Innovation Leder	Vehicle length (cm):	
License plate:	031322	Vehicle width (cm):	
Report code:	1322	Vehicle height (cm):	
Chassis number:	W0VZRHNS6KS031322	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	12/12/2018	Power(kw):	96
First NL req.:		Transmission:	Manual
Color:	Blue <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(kg):		Displacement(cc):	1200
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Leather upholstery
- Licht Sensor
- ABS
- Start/stop system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (silver)
- Metallic finish
- LED rear lights
- Exterior mirrors with step light
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Jack
- Spare wheel (homecomer)
- USB connection
- DAB+
- Bluetooth car kit
- Cruise control
- Climate control (L/R separated)
- Large screen navigation
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically adjustable driver's seat (including memory)
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Sport seats
- Ventilation driver's seat
- Ventilation passenger seat
- Extendable passenger seat
- Extendable driver's seat
- Adjustable lumbar support driver's seat
- Adjustable lumbar support passenger seat
- Audio control on the steering wheel
- Leather steering wheel
- Heated steering wheel
- Lane assistance
- Pedestrian safety system
- Dead angle assistance
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/55 R18	Michelin	5
Tire left rear	Summer	Alloy	225/55 R18	Michelin	5
Tire right front	Summer	Alloy	225/55 R18	Michelin	5
Tire right rear	Summer	Alloy	225/55 R18	Michelin	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	0	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

Clean inside (Interior is clean)

Clean outside

Damages

⊕ Not acceptable



Front bumper - Scratch



Front right rim - Scratch



Rear right rim - Scratch



Rear bumper - Ontzet



Rear left rim - Weatherworn



Front left door - Scratch

Damages

⊕ Acceptable



Tailgate/ lid - Scratch

Claimed fields

€ 0

Voorbumper / Kras(sen) / Polijsten

€ 0

RV velg / Kras(sen) / Spuiten

€ 0

RA velg / Kras(sen) / Spuiten

€ 0

Achterbumper / Ontzet / Vervangen

€ 0

Achterklep/deksel / Kras(sen) / Polijsten

€ 0

LA velg / Verweerd / Spuiten

€ 0

LV portier / Kras(sen) / Bijwerken

€ 0

Extra options



