Inspected by: Herman ATS ATS



Brand:	Ford	Mileage(km):	58082
Model:	Fiesta	Number of doors:	5
Model type:	1.0 EcoBoost Hybrid ST- Line	Vehicle length (cm):	
License plate:	R096LX	Vehicle width (cm):	
Report code:	4273	Vehicle height (cm):	
Chassis number:	WF0JXXGAHJNT24273	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	19/07/2022	Power(kw):	92
First NL req.:	26/01/2023	Transmission	Automatic
Color:	White Metallic	Number of gears	7
Weight (kg)(kg):	1251	Displacement(cc):	999
Empty weight(kg):	1151	Number of cylinders:	3
Wheelbase (cm)(cm):	249	Fuel type:	Petrol
Top speed (km/h):	199	Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	В
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):	8.9	CO2 (q/km):	1
Cargo space (I):	1251	Nb. of Axles:	2
Perm. max weight (kg):	1710	APK date:	19/07/2026

opties opties

- Alloy wheels Licht Sensor
- ABS
- Start/stop system
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Sports package (exterior)
- LED headlights
- Exterior mirrors in car body color
- Rain sensor
- Rear wiper Rear view camera
- Rear parking sensors

- Front parking sensors
 Rear-seat folding (uned
 Luggage cover
 Inflatable set
 USB connection
 - Rear-seat folding (unequal parts)

- DAB+
- ${f \checkmark}$
- **>** Bluetooth car kit
- Radio
- Cruise control
- Black top interior Climate control
- Climate control (analog)
- रारारा Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
 Electrically heated windscreen
 Electrically adjustable mirrors
 Electrically heated driver's seat
 Electrically heated passenger seat

- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Heated steering wheel
- Lane assistance
- Pedestrian safety system
- Airbag(s) front + flank + other

	Inco						
	Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):	
٦	position:	type:	type:				
	Tire left front	Summer	Alloy	205/45 R17	Continental	6	
	Tire left rear	Summer	Alloy	205/45 R17	Continental	7	
	Tire right front	Summer	Alloy	205/45 R17	Continental	6	
	Tire right rear	Summer	Allov	205/45 R17	Continental	7	

Additional information

No. of keys:	2 Luxury key	Instruction booklet		Airco works
Interior color:	Anthracite	Maintenance booklet:		Odorless
Upholstery:	Stof			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		☑ Display ok
No. of headrests:	5	Last turn mileage(km):	0	✓ Vehicle special usage (None)

A Cleaning

- Clean inside (Interior is clean)
- Clean outside

Acceptable

کر Damages



Front bumper - Scratch



Front right rim - Scratch

د Damages



Front left door - Restyle dent

← Claimed fields

Voorbumper / Kras(sen) / Spuiten



RV velg / Kras(sen) / Spuiten





































