



Brand:	Audi	Mileage(km):	64914
Model:	A1 Sportback	Number of doors:	5
Model type:	30 TFSI Advanced	Vehicle length (cm):	
License plate:	012991	Vehicle width (cm):	
Report code:	2991	Vehicle height (cm):	
Chassis number:	WAUZZZGB3MR012991	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	04/12/2020	Power(kw):	81
First NL reg.:		Transmission:	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):		Displacement(cc):	999
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control (L/R separated) |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Jack | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Inflatable set | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Airbag(s) front + flank + other |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	195/55 R16	Continental	7
Tire left rear	Winter	Alloy	195/55 R16	Continental	8
Tire right front	Winter	Alloy	195/55 R16	Continental	7
Tire right rear	Winter	Alloy	195/55 R16	Continental	8

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages

Not acceptable

🔧 Damages

🔄 Acceptable



Bonnet - Scratch



Rear left screen - Scratch

📄 Claimed fields

€ 0

Motorkap / Kras(sen) / Bijwerken

€ 0

LA scherm / Kras(sen) / Polijsten

€ 0

⚙️ Extra options





AUTOFACTOR
SOFTWARE FOR AUTOMOTIVE