



| | | | |
|---|---|-----------------------------|-----------|
| Brand: | Peugeot | Mileage(km): | 75991 |
| Model: | 3008 | Number of doors: | 5 |
| Model type: | 1.2 130PK Allure Aut. Leder | Vehicle length (cm): | |
| License plate: | 498022 | Vehicle width (cm): | |
| Report code: | 8022 | Vehicle height (cm): | |
| Chassis number: | VF3MRHNSJJS498022 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | |
| First int. reg.: | 07/01/2019 | Power(kw): | 96 |
| First NL req.: | | Transmission: | Automatic |
| Color: | Grey <input checked="" type="checkbox"/> Metallic | Number of gears: | |
| Weight (kg)(kg): | | Displacement(cc): | 1200 |
| Empty weight(kg): | | Number of cylinders: | |
| Wheelbase (cm)(cm): | | Fuel type: | Petrol |
| Top speed (km/h): | | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | | EU category: | |
| Cons. outside the city (l/100 km): | | Energy label: | |
| Average consumption (l/100 km): | | NL Tax Rate %: | |
| Acceleration (s): | | CO2 (g/km): | |
| Cargo space (l): | | Nb. of Axles: | 2 |
| Perm. max weight (kg): | | APK date: | |

opties

- Alloy wheels
- Leather upholstery
- Digital dashboard
- Licht Sensor
- ABS
- Fog lamps
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (silver)
- Metallic finish
- LED rear lights
- Exterior mirrors in car body color
- Exterior mirrors with step light
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Towbar with detachable ball
- Rear-seat folding (unequal parts)
- Luggage cover
- Trunk opens electrically
- Jack
- Spare wheel (homecomer)
- USB connection
- DAB+
- Bluetooth car kit
- Cruise control
- Climate control (digital)
- Climate control (L/R separated)
- Large screen navigation
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Adjustable lumbar support driver's seat
- Audio control on the steering wheel
- Leather steering wheel
- Pedestrian safety system
- Airbag(s) front + flank + other

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Winter | Alloy | 235/50 R18 | Bridgestone | 7 |
| Tire left rear | Winter | Alloy | 235/50 R18 | Bridgestone | 7 |
| Tire right front | Winter | Alloy | 235/50 R18 | Bridgestone | 7 |
| Tire right rear | Winter | Alloy | 235/50 R18 | Bridgestone | 7 |

Additional information

| | | | | |
|--------------------------|------------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Anthracite | Maintenance booklet: | | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Leder | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 16/02/2024 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 66047 | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable



Roof - Hail damage



Roof - Dent



Roof - Hail damage



Front left rim - Scratch



Rear right door - Restyle dent



Rear right rim - Scratch



Rear right door - Scratch



Rear bumper - Scratch




Rear left rim - Scratch



stoelzitting linksvoor slijtage

🔧 Damages

⊕ Acceptable



De Onderhouds Indicator Is Actief



Dak Lichte Hagelschade 15 X Deukje



Front left door - Restyle dent

🔪 Claimed fields

De Onderhouds Indicator Is Actief /



Dak Lichte Hagelschade 15 X Deukje /



Dak / Hagelschade / Restylen



Dak / Deuk(en) / Zo laten



Dak / Hagelschade / Restylen



LV velg / Kras(sen) / Spuiten



RV portier / Restyle Deukje(s) / Restylen



RA portier / Restyle Deukje(s) / Restylen en bijwerken



RA velg / Kras(sen) / Spuiten



RA portier / Kras(sen) / Bijwerken



Achterbumper / Kras(sen) / Spuiten



LA velg / Kras(sen) / Spuiten



⚙️ Extra options

