



Brand:	Hyundai	Mileage(km):	56016
Model:	Kona	Number of doors:	5
Model type:	1.6 Hybrid 140PK Business Aut.	Vehicle length (cm):	
License plate:	075461	Vehicle width (cm):	
Report code:	5461	Vehicle height (cm):	
Chassis number:	KMHK381EGMU075461	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	03/12/2021	Power(kw):	103
First NL req.:		Transmission	Automatic
Color:	Anthracite <input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1600
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Hybride (Electro/Benzine) non plug-in
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Digital dashboard
- Licht Sensor
- ABS
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Roof rail (black)
- Metallic finish
- Exterior mirrors in car body color
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Inflatable set
- USB connection
- DAB+
- Bluetooth car kit
- Cruise control
- Climate control (digital)
- Large screen navigation
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Switch flippers
- Lane assistance
- Pedestrian safety system
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/60 R16	Kleber Allseason	7
Tire left rear	Summer	Alloy	205/60 R16	Nexen	6
Tire right front	Summer	Alloy	205/60 R16	Kleber Allseason	7
Tire right rear	Summer	Alloy	205/60 R16	Nexen	6

Additional information

No. of keys:	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	25/11/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	52650	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside (Polishing)

🔧 Damages

⊕ Not acceptable



Front bumper - Dent



Front bumper - Scratch



Right headlight - Scratch



Front bumper - Scratch



Front left door - Dent



Rear right door - Restyle dent




Rear bumper - Scratch

🔧 Damages

⊕ Acceptable



Voorzijde Allseason Banden En Achterzijde Zomerbanden



Rear left screen - Restyle dent



Rear left door - Restyle dent



Front left screen - Restyle dent

👉 Claimed fields

€ 0

Voorzijde Allseason Banden En
Achterzijde Zomerbanden /



Voorbumper, Voorbumper / Deuk(en),
Deuk(en) / Spuiten



Voorbumper, Voorbumper / Kras(sen),
Kras(sen) / Spuiten



Koplamp rechts, Koplamp rechts /
Kras(sen), Kras(sen) / Spuiten



Voorbumper, Voorbumper / Kras(sen),
Kras(sen) / Spuiten



RV portier, RV portier / Deuk(en),
Deuk(en) / Restylen



RA portier, RA portier / Restyle
Deukje(s), Restyle Deukje(s) / Restylen



Achterbumper, Achterbumper /
Kras(sen), Kras(sen) / Spuiten



LA scherm, LA scherm / Restyle
Deukje(s), Restyle Deukje(s) / Restylen



LA portier, LA portier / Restyle
Deukje(s), Restyle Deukje(s) / Restylen



LV scherm, LV scherm / Restyle
Deukje(s), Restyle Deukje(s) / Restylen



⚙️ Extra options

