



Brand:	Mitsubishi	Mileage(km):	52761
Model:	Space Star	Number of doors:	5
Model type:	1.0 Bright	Vehicle length (cm):	
License plate:	HB263N	Vehicle width (cm):	
Report code:	0551	Vehicle height (cm):	
Chassis number:	MMCXNA05AFH110551	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	05/10/2015	Power(kw):	52
First NL reg.:	05/10/2015	Transmission:	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	5
Weight (kg)(ka):	920	Displacement(cc):	999
Empty weight(ka):	820	Number of cylinders:	3
Wheelbase (cm)(cm):	245	Fuel type:	Petrol
Top speed (km/h):	172	Fuel tank capacity:	
Cons. in the city (l/100 km):	4.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.6	Energy label:	A
Average consumption (l/100 km):	4	NL Tax Rate %:	25
Acceleration (s):	13.6	CO2 (g/km):	92
Cargo space (l):	920	Nb. of Axles:	2
Perm. max weight (kg):	1290	APK date:	05/10/2025

opties

- Alloy wheels
- Licht Sensor
- ABS
- Fog lamps
- Start/stop system
- Power steering
- Remote central locking
- Metallic finish
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Towbar with fixed ball
- Rear-seat folding (unequal parts)
- Luggage cover
- Inflatable set
- Aux connection
- Radio/CD player
- Radio/CD/MP3 player
- Climate control (analog)
- Electrically operated rear windows
- Electrically operated front windows
- Electrically adjustable mirrors
- Leather steering wheel
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	165/65 R14	Vredestein	7
Tire left rear	Summer	Alloy	165/65 R14	Bridgestone	7
Tire right front	Summer	Alloy	165/65 R14	Vredestein	7
Tire right rear	Summer	Alloy	165/65 R14	Bridgestone	7

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	03/10/2023	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	44110	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages

Not acceptable



Roof - Restyle dent



Front left door - Restyle dent

🔧 Damages

🟢 Acceptable



De Onderhouds Indicator Is Actief



Front bumper - Scratch



Rear right screen - Restyle dent



Rear bumper - Scratch



Rear left screen - Scratch



Left B- column - Scratch

🏠 Claimed fields

€ 0

De Onderhouds Indicator Is Actief /

€ 0

Voorbumper / Kras(sen) / Spuiten

€ 0

Dak / Restyle Deukje(s) / Restylen

€ 0

RA scherm / Restyle Deukje(s) / Restylen

€ 0

Achterbumper / Kras(sen) / Polijsten

€ 0

LA scherm / Kras(sen) / Polijsten

€ 0

LV portier / Restyle Deukje(s) / Restylen en bijwerken



€ 0

B-Stijl links / Kras(sen) / Bijwerken

€ 0

⚙️ Extra options







AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE