



Brand:	Seat	Mileage(km):	24483
Model:	Tarraco	Number of doors:	5
Model type:	1.4 PHEV FR Aut. Pano	Vehicle length (cm):	
License plate:	500131	Vehicle width (cm):	
Report code:	0131	Vehicle height (cm):	
Chassis number:	VSSZZKZNW500131	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	16/12/2021	Power(kw):	
First NL reg.:		Transmission	Automatic
Color:	Anthracite <input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(ka):		Displacement(cc):	1400
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Hybride (Electro/Benzine) plug-in
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Avarage consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- | | | |
|--|---|--|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Automatic parking system | <input checked="" type="checkbox"/> Keyless start/stop |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Ski hatch | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically adjustable driver's seat (including memory) |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Trunk opens electrically | <input checked="" type="checkbox"/> Electrically heated driver's seat |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Charging cable 380V | <input checked="" type="checkbox"/> Electrically heated passenger seat |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Charging cable 220V | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Roof rail (black) | <input checked="" type="checkbox"/> Inflatable set | <input checked="" type="checkbox"/> Sport seats |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Panoramic roof (electrical) | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Cruise control (adaptive) | <input checked="" type="checkbox"/> Leather sports steering wheel |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Sports package (interior) | <input checked="" type="checkbox"/> Switch flippers |
| <input checked="" type="checkbox"/> Exterior mirrors with step light | <input checked="" type="checkbox"/> Black top interior | <input checked="" type="checkbox"/> Heated steering wheel |
| <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Airconditioning in the back | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control (digital) | <input checked="" type="checkbox"/> Pedestrian safety system |
| <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control (L/R separated) | <input checked="" type="checkbox"/> Dead angle assistance |
| <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Large screen navigation | <input checked="" type="checkbox"/> Airbag(s) front + flank + other |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	255/40 R20	Pirelli	7
Tire left rear	Summer	Alloy	255/40 R20	Pirelli	9
Tire right front	Summer	Alloy	255/40 R20	Pirelli	7
Tire right rear	Summer	Alloy	255/40 R20	Pirelli	9

Additional information

No. of headlights:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages

⊕ Not acceptable



Front right rim - Scratch



Rear right rim - Scratch



Rear bumper - Scratch



Rear left rim - Scratch



Front left door - Restyle dent

Damages

⊕ Acceptable



Diverse Lampjes Actief Ivm Lege Accu



Front left rim - Scratch

Claimed fields

€ 0

Diverse Lampjes Actief Ivm Lege Accu /

€ 0

LV velg / Kras(sen) / Spuiten

€ 0

RV velg / Kras(sen) / Spuiten

€ 0

RA velg / Kras(sen) / Spuiten

€ 0

Achterbumper / Kras(sen) / Spuiten

€ 0

LA velg / Kras(sen) / Spuiten

€ 0

LV portier / Restyle Deukje(s) / Restylen

€ 0

Extra options



