



Brand:	Peugeot	Mileage(km):	42923
Model:	Rifter	Number of doors:	5
Model type:	XL 1.2 Allure	Vehicle length (cm):	
License plate:	784071	Vehicle width (cm):	
Report code:	4071	Vehicle height (cm):	
Chassis number:	VR3ERHNP2KJ784071	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	16/10/2019	Power(kw):	81
First NL reg.:		Transmission:	Manual
Color:	White <input type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):		Displacement(cc):	1200
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Licht Sensor
- ABS
- Fog lamps
- Start/stop system
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Roof rail (silver)
- Exterior mirrors in car body color
- Rain sensor
- Rear wiper
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Jack
- Spare wheel (full)
- Bluetooth car kit
- Radio
- Cruise control
- Airconditioning in the back
- Climate control (digital)
- Large screen navigation
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Audio control on the steering wheel
- Lane assistance
- Pedestrian safety system
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Steel	215/65 R16	Michelin	5
Tire left rear	Summer	Steel	215/65 R16	Michelin	6
Tire right front	Summer	Steel	215/65 R16	Michelin	5
Tire right rear	Summer	Steel	215/65 R16	Michelin	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside (Cleaning)

Damages

Not acceptable



Front left door - Dent

🔧 Damages

⊕ Acceptable



De Onderhouds Indicator Is Actief



Geen Servicepas Aanwezig



Left outside mirror - Scratch

👉 Claimed fields

€ 0

De Onderhouds Indicator Is Actief /

€ 0

Geen Servicepas Aanwezig /

€ 0

LV portier / Deuk(en) / Spuiten

€ 0

Buitenspiegel links / Kras(sen) / Polijsten

€ 0

⚙️ Extra options



