



Brand:	Opel	Mileage(km):	27729
Model:	Corsa-E	Number of doors:	5
Model type:	Level 2 50 kWh	Vehicle length (cm):	
License plate:	S319VG	Vehicle width (cm):	
Report code:	0509	Vehicle height (cm):	
Chassis number:	VXKHZKXZP4070509	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	19/04/2023	Power(kw):	100
First NL reg.:	19/04/2023	Transmission:	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):	1530	Displacement(cc):	
Empty weight(ka):	1430	Number of cylinders:	
Wheelbase (cm)(cm):	254	Fuel type:	Electric
Top speed (km/h):	150	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	A
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):	8.1	CO2 (g/km):	1
Cargo space (l):	1530	Nb. of Axles:	2
Perm. max weight (kg):	1920	APK date:	19/04/2027

opties

- Licht Sensor
- ABS
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Metallic finish
- Exterior mirrors in car body color
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Rear-seat folding (unequal parts)
- Baggage separation net
- Charging cable 220V
- Inflatable set
- USB connection
- DAB+
- Bluetooth car kit
- Radio
- WiFi
- Cruise control
- Climate control
- Climate control (digital)
- Climate control (L/R separated)
- Large screen navigation
- Keyless entry
- Keyless start/stop
- Electrically operated front windows
- Electrically adjustable mirrors
- Lane assistance
- Pedestrian safety system
- Airbag(s) front
- Airbag(s) front + flank

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather		195/55 R16	Continental	4
Tire left rear	All weather		195/55 R16	Continental	6
Tire right front	All weather		195/55 R16	Continental	4
Tire right rear	All weather		195/55 R16	Continental	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
Interior color:	Anthracite	Maintenance booklet:	(door dealer)	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	04/10/2023	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	14320	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

Damages

⊕ Not acceptable



Front left screen - Restyle dent

Damages

Acceptable



Rear bumper - Scratch



Rear bumper - Scratch



Rear left screen - Stone chippings



Front left door - Scratch

Claimed fields

€ 0

Achterbumper / Kras(sen) /

€ 0

Achterbumper / Kras(sen) /

€ 0

LA scherm / Steenslag /

€ 0


LV portier / Kras(sen) /

€ 0

RV scherm / Restyle Deukje(s) / Restylen

€ 0

Extra options





AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE