



Brand:	Volvo	Mileage(km):	48596
Model:	XC40	Number of doors:	5
Model type:	1.5 T4 Recharge Core aut. pano	Vehicle length (cm):	
License plate:	85561	Vehicle width (cm):	
Report code:	5561	Vehicle height (cm):	
Chassis number:	YV1XZBWVFM2585561	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	15/04/2021	Power(kw):	
First NL req.:		Transmission	Automatic
Color:	<input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(kg):		Displacement(cc):	1499
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Hybride (Electro/Benzine) plug-in
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Digital dashboard
- Daytime running lights
- Licht Sensor
- ABS
- Fog lamps
- Start/stop system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Roof rail (silver)
- Metallic finish
- Panoramic roof (electrical)
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Inflatable set
- USB connection
- Bluetooth streaming
- Bluetooth car kit
- Radio
- Cruise control (adaptive)
- Climate control (digital)
- Large screen navigation
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Lane assistance
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	/	Continental	4
Tire left rear	Summer	Alloy	/	Continental	3
Tire right front	Summer	Alloy	/	Continental	4
Tire right rear	Summer	Alloy	/	Continental	3

Additional information

No. of keys:	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)
- Clean outside

🔧 Damages

⊕ Not acceptable

🔧 Damages

⊕ Acceptable



Rear bumper - Scratch



Front bumper - Scratch



Front right rim - Scratch



Rear right rim - Scratch



Rear right door - Dent



Tailgate/ lid - Dent



Voertuig rondom - Hail damage



Roof - Hail damage

🔧 Claimed fields

€ 0

Achterbumper / Kras(sen) /

€ 0

Voorbumper / Kras(sen) /

€ 0

RV velg / Kras(sen) /

€ 0

RA velg / Kras(sen) /

€ 0

RA portier / Deuk(en) /

€ 0

Achterklep/deksel / Deuk(en) /

€ 0

Voertuig rondom / Hagelschade /

€ 0

Dak / Hagelschade /

€ 0

⚙️ Extra options



