



| | | | |
|---|---|-----------------------------|-----------------------------------|
| Brand: | Mercedes-Benz | Mileage(km): | 46919 |
| Model: | GLA 250 | Number of doors: | 5 |
| Model type: | e AMG Line Aut. Pano | Vehicle length (cm): | |
| License plate: | 440155 | Vehicle width (cm): | |
| Report code: | 0155 | Vehicle height (cm): | |
| Chassis number: | W1N4N8GB5PJ440155 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | |
| First int. reg.: | 14/10/2022 | Power(kw): | 118 |
| First NL reg.: | | Transmission: | Automatic |
| Color: | Grey <input type="checkbox"/> Metallic | Number of gears: | |
| Weight (kg)(ka): | | Displacement(cc): | 1300 |
| Empty weight(ka): | | Number of cylinders: | |
| Wheelbase (cm)(cm): | | Fuel type: | Hybride (Electro/Benzine) plug-in |
| Top speed (km/h): | | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | | EU category: | |
| Cons. outside the city (l/100 km): | | Energy label: | |
| Average consumption (l/100 km): | | NL Tax Rate %: | |
| Acceleration (s): | | CO2 (g/km): | |
| Cargo space (l): | | Nb. of Axles: | 2 |
| Perm. max weight (kg): | | APK date: | |

opties

- Alloy wheels
- Digital dashboard
- Daytime running lights
- Licht Sensor
- ABS
- Dynamic bend lighting
- Start/stop system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Roof rail (black)
- Panoramic roof (electrical)
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Exterior mirrors with step light
- Privacy glass
- Rain sensor
- Rear wiper
- 360 ° camera system
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Trunk opens electrically
- Charging cable 380V
- Charging cable 220V
- Inflatable set
- USB connection
- Bluetooth streaming
- DAB+
- Bluetooth car kit
- Radio
- Cruise control
- Black top interior
- Climate control (digital)
- Large screen navigation
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Extendable driver's seat
- Audio control on the steering wheel
- Leather steering wheel
- Switch flippers
- Lane assistance
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Summer | Alloy | / | Bridgestone | 6 |
| Tire left rear | Summer | Alloy | / | Bridgestone | 6 |
| Tire right front | Summer | Alloy | / | Bridgestone | 6 |
| Tire right rear | Summer | Alloy | / | Bridgestone | 5 |

Additional information

| | | | | |
|--------------------------|-----------------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Black | Maintenance booklet: | | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Half stof/leder | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning

Clean inside (Interior is clean)

Clean outside

🔧 Damages

⊗ Not acceptable

🔧 Damages

⊗ Acceptable



Rear right rim - Scratch



Front right rim - Scratch



Front bumper - Scratch



Front left rim - Scratch



Rear left rim - Scratch

🔧 Claimed fields

€
0

RA velg / Kras(sen) /

€
0

RV velg / Kras(sen) /

€
0

Voorbumper / Kras(sen) /

€
0

LV velg / Kras(sen) /

€
0

LA velg / Kras(sen) /

€
0

⚙️ Extra options





