



Brand:	Kia	Mileage(km):	49918
Model:	Rio	Number of doors:	5
Model type:	1.0 100PK GT-Line	Vehicle length (cm):	
License plate:	574634	Vehicle width (cm):	
Report code:	4634	Vehicle height (cm):	
Chassis number:	KNADE517AM6574634	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	12/08/2021	Power(kw):	74
First NL reg.:		Transmission:	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(ka):		Displacement(cc):	999
Empty weight(ka):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Petrol
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- Alloy wheels
- Daytime running lights
- Licht Sensor
- ABS
- Dynamic bend lighting
- Fog lamps
- Start/stop system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Metallic finish
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Privacy glass
- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts)
- Luggage cover
- Spare wheel (full)
- USB connection
- Bluetooth streaming
- DAB+
- Bluetooth car kit
- Radio
- Cruise control
- Climate control (analog)
- Large screen navigation
- Keyless entry/start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Heated steering wheel
- Lane assistance
- Airbag(s) front
- Airbag(s) front + flank
- Airbag(s) front + flank + other

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	/	Continental	7
Tire left rear	All weather	Alloy	/	Vredestein	5
Tire right front	All weather	Alloy	/	Continental	5
Tire right rear	All weather	Alloy	/	Vredestein	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	19/05/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	49255	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)

Clean outside

⚙ Damages

⊕ Not acceptable

⚙ Damages

⊕ Acceptable



Rear left rim - Scratch



Front left rim - Scratch



Front bumper - Scratch



Rear bumper - Paint repair



Rear right rim - Scratch



Rear right door - Scratch



Front right rim - Scratch

🔍 Claimed fields

€ 0

LA velg / Kras(sen) / Spuiten

€ 0

LV velg / Kras(sen) /

€ 0

Voorbumper / Kras(sen) /

€ 0

Achterbumper / Lakherstel /

€ 0

RA velg / Kras(sen) /

€ 0




RA portier / Kras(sen) /

€ 0

RV velg / Kras(sen) /

€ 0

⚙ Extra options





AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE