



Brand:	Mercedes-Benz	Mileage(km):	53855
Model:	GLA 250	Number of doors:	5
Model type:	e AMG-Line Aut.	Vehicle length (cm):	
License plate:	185727	Vehicle width (cm):	
Report code:	5727	Vehicle height (cm):	
Chassis number:	W1N2477861J185727	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	
First int. reg.:	09/10/2020	Power(kw):	160
First NL reg.:		Transmission:	Automatic
Color:	White <input type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(kg):		Displacement(cc):	1300
Empty weight(kg):		Number of cylinders:	
Wheelbase (cm)(cm):		Fuel type:	Hybride (Electro/Benzine) plug-in
Top speed (km/h):		Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):		CO2 (g/km):	
Cargo space (l):		Nb. of Axles:	2
Perm. max weight (kg):		APK date:	

opties

- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Keyless entry/start/stop |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Dynamic bend lighting | <input checked="" type="checkbox"/> Trunk opens electrically | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Charging cable 380V | <input checked="" type="checkbox"/> Electrically heated driver's seat |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Charging cable 220V | <input checked="" type="checkbox"/> Electrically heated passenger seat |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Inflatable set | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Extendable passenger seat |
| <input checked="" type="checkbox"/> Roof rail (black) | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Extendable driver's seat |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Switch flippers |
| <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Black top interior | <input checked="" type="checkbox"/> Airbag(s) front |
| <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control (analog) | <input checked="" type="checkbox"/> Airbag(s) front + flank |
| <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Large screen navigation | <input checked="" type="checkbox"/> Airbag(s) front + flank + other |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	/	Bridgestone	5
Tire left rear	All weather	Alloy	/	Bridgestone	6
Tire right front	All weather	Alloy	/	Bridgestone	5
Tire right rear	All weather	Alloy	/	Bridgestone	6

Additional information

No. of keys:	1 <input type="checkbox"/> Luxury key <input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder	<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5 Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5 Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- Clean inside (Interior is clean)

Clean outside

🔧 Damages

⊕ Not acceptable

🔧 Damages

⊕ Acceptable



Rear right rim - Scratch



Rear right door - Dent



Front right rim - Scratch



Front bumper - Scratch



Front left rim - Scratch

🔍 Claimed fields

€ 0

RA velg / Kras(sen) /

€ 0

RA portier / Deuk(en) /

€ 0

RV velg / Kras(sen) /

€ 0

Voorbumper / Kras(sen) /



€ 0

LV velg / Kras(sen) /

€ 0

⚙️ Extra options







AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE